

ASS. PEO. BY:

REF:

CS/FCI22011449/D94<sup>3</sup>

ASSIGNMENT

C/E 2029 March

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 8JW 1077H Yr Regn: 2010 / March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180K cc 1796

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 142112 T/Radio: Insured / Std / NI / NA

Eng/No: 27191031301073

C/No: WDD2040452A356180

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front R/Bal. 5 mm Rear R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 12/11/2022 D.O.I. 21/11/2022

Survey held at JWG AMC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First Capital GRK 7131C.
22/02/23	Invoice 215 5,500/- with 5 days of rep Used @ 51245.10, 96%
	19940

Date/Time, File Pass to?  : Preli. Report  
11/23/23  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Report Form: 7p

Days Of Repair: 5  
Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Inve (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S + RS: \_\_\_\_\_  
Photos: \_\_\_\_\_  
Others: \_\_\_\_\_

46 x 15 = 690
690 + 170
50
50
61
1021

JSA  
CSJ 22/2/23