

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 41774

at Workshop m/s Volkswagen

of 247, ALGEMERE RD

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

1.30

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 75K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 41774 Yr Regn: 2017 / NBL

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf 1.2TSI c.c. 1197

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 43386 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW222AU24W 122047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 09/11/22

D.O.I. 16/11/22

Survey held at Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 47K

Rasul finalised final fig \$12666.49, 6 days. (Red \$7913.72, 38%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 06/01 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format : MER-TP

Lump Sum / I.B.I: (\$ 12666.49)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
KANDESAN
S/O RAMASAMY
308 TAMPINES STREET 32
#08-114
Singapore 520308

Document no.
Document date 14-11-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022033068/ 1
Job order date 12-11-2022
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLU4177U	5G12BZ	30-11-2017	WVWZZZAUZHW122047	Golf 1.2 TLBM 81 TSI D7F	41,825

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
D 169300M2	1k Window Adhesive	2	pcs.	51.44	#1	102.88	110.08
D 00940104	All Purpose Cleaner	1	pcs.	102.88	#1	102.88	110.08
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 181802M1	Activator	1	pcs.	26.27	#1	26.27	28.11
D 00950025	Applicator	2	pcs.	11.16	#1	22.32	23.88
5G6827025Q	Rear Trunk Lid	1	pcs.	3,184.78	#1	3,184.78	3,407.71
5G6827505B 9B9	Hood Latch Satin Black BOOT LID LOCK	1	pcs.	266.89	#1	266.89	285.57
5G6827469F FOD	Oper.Mechan.With Micro Sw	1	pcs.	802.61	#1	802.61	858.79
510827861A	Water Drain Hose	1	pcs.	9.54	#1	9.54	10.21
5G6827705E	Gasket BOOT WETHERSTRIP	1	pcs.	299.42	#1	299.42	320.38
5G0945087B	Additional Brake Light W/ 3RD BRAKELIGHT	1	pcs.	183.08	#1	183.08	195.90
5G0945093AD	Taillight LHS TAILLIGHT INNER	1	pcs.	317.12	#1	317.12	339.32
5G0853687 2ZZ	Inscription Bright Chrome NAME PLATE - GOLF	1	pcs.	89.77	#1	89.77	96.05
5G0853675AR2ZZ	Inscription Bright Chrome NAME PLATE - 180 TSI	1	pcs.	81.11	#1	81.11	86.79
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,417.50	#1	1,417.50	1,516.73
5G6807568B 9B9	Rear Diffusor Satin Black	1	pcs.	361.39	#1	361.39	386.69
WHT005263	Rivet	4	pcs.	1.32	#1	5.28	5.65
5G0807305D	Bumper REINFORCEMENT	1	pcs.	750.84	#1	750.84	803.40
5G6807863C	Attachment Strip BUMPER CTR BRACKET	1	pcs.	73.18	#1	73.18	78.30
5G6807393A	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	#1	43.33	46.36
5G6807394A	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	#1	43.33	46.36
5G6807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	#1	43.33	46.36
5G6807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	#1	43.33	46.36
1K8943021	License Plate Light	2	pcs.	44.37	#1	88.74	94.95
5G0945105	Reflector REFLECTOR LH	1	pcs.	81.02	#1	81.02	86.69
	LABOUR	82	pcs.	840.00	#1	5,940.00	5,392.80
	SPRAY PAINT	82	pcs.	800.00	#1	4,000.00	4,280.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
KANDESAN
S/O RAMASAMY
308 TAMPINES STREET 32
#08-114
Singapore 520308

Document no.
Document date 14-11-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022033068/ 1
Job order date 12-11-2022
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLU4177U	5G12BZ	30-11-2017	WVWZZZAUZH122047	Golf 1.2 TLBM 81 TSI D7F	41,825

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REAR NAMBER PLATE 64 ✓	1	pcs.	80.00	#1	80.00	85.60
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	INCOME VS CHINA TAIPING						
	3RD PARTY VEHICLE GBL950X						
	D.O.A: 09-11-2022						
	SURVEY BY:						

Quotation valid till 19-11-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	19,820.21	7%	1,440.61	20,580.21	22,020.82
Total	760.00	19,820.21		1,440.61	20,580.21	22,020.82

Customer

14/11/22



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Rasul
Hp 90010068
5 days
P/P
16/11/22 @ 1410
Raz Selam part

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/11/2022 19:23 (SGT)
Reported by Driver
Date of Accident 09/11/2022 14:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information Along Paya Lebar Road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU4177U
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner KANDESAN S/O RAMASAMY
NRIC No S1511102Z
Email Address rkandesan@gmail.com
Mobile Phone No (Phone) +65-94381961
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Golf
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1200

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited
Policy Number / Cover Note Number 5112928154-02

DRIVER

Name of Driver KALAIVANI D/O KANDESAN
NRIC No S8728552I
Date Of Birth 16/09/1987
Occupation Indoor

any
w/s
Income
vs
Claim
Tapping
no
claim
injury.

Valid Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

25/09/2007
15 YEARS AND 2 MONTHS
Female
(Phone) +65-90482744
-
rkandesan@gmail.com
308 TAMPINES STREET 32
#08-114
S520308
No
Child
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?
Translator's name
Translator's ID
Translator's phone number
Translator's email
Original language used in the statement

No
2
No
-
Yes
1
No
-
-
-
-
-

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

Refer to sketch plan

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?

Yes
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number

GBL950X
-
-
-
-
Commercial vehicle
-
(Phone) +65-90967090

Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report ~~promptly~~ the status of the accident to speed up the claim process.
2. This Form must be completed by the ~~Personnel~~ Insurance Company.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may cause insurance companies to cancel the policy.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and its copies of the report being made available to them.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My Insurer, my Insurers and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data (personal information) as in this Form and any other personal information provided by me or collected by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers and have insured vehicles involved in this accident (all insurers who have insured vehicles) involved in this accident and be collectively referred to as the "Insurers", the Insurers' cooperation firms, the Monetary Authority of Singapore and any relevant government agency authority (such as the police), for the purposes of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or the claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or policies to me, which could involve disclosure of other personal data about me to third parties delivery of the same as well as on the external cover of correspondence and/or packages) and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all Insurers who have insured vehicles involved in this accident and the Insurers' cooperation firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their Insurers' firms), which may be used outside of Singapore, for one or more of the above Purposes.

Vanu


Officer's Signature: I am the authorised signatory.
Date: 10/11/2022 19:40 hr

1401 (Chang Ching)

Witnessed by Reporting Centre Personnel
(Name as in NRIC: Q. card)

PERSONAL DATA: Date & Time

Sketch Plan



Describe Circumstances of the Accident

I was travelling on the lane along Paya Lebar Road,
I came to a stop before the junction when traffic light
turn red, but at sudden I felt an impact from my rear
and realized vehicle B collided onto my vehicle
from rear.

Declaration

I hereby declare the foregoing particulars are true to the best of my knowledge.

Witness's Signature: [Signature]

Driver's Signature: [Signature]
Date: 10/11/2022 1500 hrs

Witnessed by: [Signature]
Name: [Name]
Address: [Address]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	102Z

Vehicle No.:	SLU4177U
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.2 TSI AT 5G12BZ
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CYV515349
Chassis No.:	WWWZZZAUZHW122047
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,773.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,773.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2027
PARF Rebate Amount:	\$4,329.00

COE Expiry Date:	29 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$23,538.00
Total Rebate Amount:	\$27,867.00

The information contained herein is correct as at 18 Nov 2022

OK

Volkswagen Golf 1.2A TSI

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$75,500****Depreciation** ⓘ

\$14,480 /yr

[View models with similar depre](#)**Reg Date**

24-Nov-2017

(5yrs 5days COE left)

Mileage

59,000 km (11.8k /yr)

Manufactured ⓘ

2016

Road Tax ⓘ

\$508 /yr

Transmission

Auto

Dereg Value ⓘ

\$27,963 as of today (change)

OMV ⓘ

\$15,773

COE ⓘ

\$47,112

ARF ⓘ

\$5,773

Engine Cap

1,197 cc

Power

81.0 kW (108 bhp)

Curb Weight ⓘ

1,229 kg

No. of Owners ⓘ

1

Type of Vehicle

Hatchback