

 Service Request Details

Claim	S2M04DTQ
Reference	CS/ASM22011456/Uny3m4 
Loss Date	28 October 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	1 Nov 2022 10:52:01 AM
Request Date	15 November 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	FBF4802X
Vehicle	
Registration #	
Make	TPVD Yamaha
Model	Fz16

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2207258.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2022
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2022
 FBF 4802X-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 November 2022
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	10 November 2022
 TP GIA FBF4802X.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	1 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 INSD GIA SHC2307S.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	31 October 2022