

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GST Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURAI	NCE PTE LTD		Ref:	CS3/CWF22001964/Cvy3e2-1	
		& CO. INTERNATIONAL PL AY, #19-10 OUE DOWNTOWN2 09		Date:	16/12/2022	
				Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	TREE BRANCH FELL	Veh. Inspected		SLV 4391L	
	Policy No.	1095870/G/KY	Coverage (\$)		0.00	
	Claim No.	ALS22/0006	Excess (\$)		0.00	
	Assign From	KENNETH YEE	Assign Date		14/11/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA NIRO	c.c		1580	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KNACC81CVJ5149528	Colour		BLUE	
	Odometer	36307 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	225/50 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/50 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/50 R17	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/02/2022	Inspection Dat	е	02/03/2022	
	Survey held at	CAR CITY AUTO CENTRE PTE	LTD			
		BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

20 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: