



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |  |   |                               |                    |
|--|--|---|-------------------------------|--------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909 |  |   | Ref: CS3/CTI22003343/Cvy3e2-1 |                    |
|  |  |   | Date: 08/12/2022              |                    |
|  |  |   | Code: CTI                     |                    |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |   |                               |                    |
|  | <b>Insured Veh.</b>  | SMV 6621Z   | <b>Veh. Inspected</b>         | SMD 2701Y          |
|  | <b>Policy No.</b>  | DMPCSNW00198042100  | <b>Coverage (\$)</b>          | 0.00               |
|  | <b>Claim No.</b>   | SNM22D202457/C02  | <b>Excess (\$)</b>            | 0.00               |
|  | <b>Assign From</b>   | ADELINE CHNG  | <b>Assign Date</b>            | 11/11/2022         |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |   |                               |                    |
|  | <b>Make &amp; Model</b>  | KIA FORTE K3  | <b>c.c</b>                    | 1591               |
|  | <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>           | 2015               |
|  | <b>Chassis No.</b>   | KNAFZ411MF5452749   | <b>Colour</b>                 | WHITE              |
|  | <b>Odometer</b>  | 117950 KM   | <b>Steering</b>               | IN ORDER           |
|  | <b>Brakes</b>  | IN ORDER  | <b>Modification</b>           | STANDARD ALLOY RIM |
|  | <b>General</b>   | GOOD  |                               |                    |
| <b>3. Conditions of Tyres</b>  |  |   |                               |                    |
|  |  | <b>Size</b>   | <b>Make</b>                   | <b>Balance</b>     |
|  | <b>R/H Front Tyre</b>  | 215/45 R17  | MICHELIN                      | 6 mm               |
|  | <b>L/H Front Tyre</b>  | 215/45 R17  | MICHELIN                      | 6 mm               |
|  | <b>R/H Rear Tyre</b>   | 215/45 R17  | MICHELIN                      | 6 mm               |
|  | <b>L/H Rear Tyre</b>   | 215/45 R17  | MICHELIN                      | 6 mm               |
| <b>4. Description of Damages</b>   |  |   |                               |                    |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                               |                    |
| <b>5. General Information</b>  |  |   |                               |                    |
|  | <b>Accident Date</b>   | 10/04/2022  | <b>Inspection Date</b>        | 12/04/2022         |
|  | <b>Survey held at</b>  | GARAGE 13 PTE LTD<br>8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 |                               |                    |
| <b>5a. Remarks</b>   |  |   |                               |                    |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                               |                    |
| <b>5b. Estimate Days of Repair</b>   |  |   |                               |                    |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>7 Working Days</b>         |                    |