TRANSPORT ASSESSMENT REPORT (TAR) INVOLVING A 5 TON (MID 20935) & SHD3095R ALONG PIONEER ROAD NORTH AROUND 1036 HRS ON 08 NOVEMBER 2022




Fig 1A: Schematic Diagram of Incident




Figure 1B: Schematic Diagram of Incident




Figure 1C: Schematic Diagram of Incident




Figure 1D: Schematic Diagram of Incident



Figure 2A: Front View of MID 20935



Figure 2B: Rear View of MID 20935



Figure 2C: Side View of MID 20935



Figure 2D: Side View of MID 20935



Figure 2E: Zoom in damage on LHS Front Bumper of (5TON) MID20935




Figure 2F: Front view of SHD3095R




Figure 2G: Rear view of SHD3095R



Figure 2H: Side view of SHD3095R



Figure 2I: Side view of SHD3095R

STATEMENT OF TRANSPORT OPERATOR SINGAPORE ARMED FORCES

								_			
STATEM	ENT OF	CPL LIM CHIN F	ENG					AL	LASES	N/A	
NRIC NO	o	JTXXXXX232A	AGE			21	M		LE/FEMALE	Male	
EMPLO	YMENT	NSF	DRIVING LICENCE		SAF	/TPT/006	0060/22 N		TIONALITY	SINGAPORE	
DIALEC	т	-	LANGUA SPOKEN	GE	ENGLI	SH	TE		LNO	-	
ADDRES	SS										
RECORI	DED BY	JAYEN NG	RANK	LTA	TIME	1552	DATE		081122	SIGN	N/A
the right of the i was too comma	nt turn to PI ncoming tr o close and inder and I	ened about 10 E Expressway affic, the vehi crashed onto was not injure o say for myse	when tricle commends the left and the left a	affic lig nander	tht turn CPT Ja	green, i son sho	I follov outed t	ved o asi	the traffic bu k me to stop	t was no but the	t aware vehicle
DATE	081122		SIGNATUI DRIVER/V		;	<u> </u>	<sent td="" vi<=""><td>a em</td><td>ail>></td><td></td><td></td></sent>	a em	ail>>		

Figure 3A: Statement of Driver

STATEMENT OF VEHICLE COMMANDER SINGAPORE ARMED FORCES

STATEM	ENT OF	CPT JASON FOO	YONG HA	10				AL	LASES	N/A	
NRIC N	0	SXXXX728C	AGE			28		MALE/FEMALE		Male	
EMPLO	YMENT	REG	DRIVING LICENCE			-		NATIONALITY		SINGAPORE	
DIALEC	т	-	LANGUA SPOKEN	GE	ENGLI	SH		TE	LNO		
ADDRE	SS										
RECOR	DED BY	JAYEN NG	RANK	LTA	TIME	1552	DATE		081122	SIGN	N/A
roads. I deployr and I sh tonner. The tax Ambula and atte At arou	Prior to the ament at MUT nouted for the Howver, the indriver was callended to the cond 1126hrs,	casualty was ta proceed to the	s using med using; s vehicle is ght ahead the collise and police ken to NU medical collise Left eye	ay phone my phone immedia d and hit ion with was info JH. entre aft Left Tr tenderne transient	e for na- ne, I saw ntely. The onto the nminor b ormed at er advise capezius sss, need	vigation the inco e TO tri e front o bleeding 1050hr: ed by my	a and li- oming ta- ied to fo of the less on his s. At 10. y superi	aisin ixi tr illow A sid head 50hr	g matters reg avelling at an my instruction to passenger so to s, Ambulance	arding (increasi ons to sto eat.	OPFORs ng speed op the 5- on scene
DATE	081122		SIGNATUI DRIVER/V			4	< <sent td="" vi<=""><td>a em</td><td>ail>></td><td></td><td></td></sent>	a em	ail>>		

Figure 3B: Statement of Vehicle Commander

	SINGAPOR POLICE FO							108/7035	
Police Station Traffic Police 10 Ubi Avenu Tel No: 6547	ue 3 SINGAPOF	RE 408865					Repor	1 of 3 1 No. T/20221108/70	
REPORT OF A	TRAFFIC ACCIDE	:NT	Vide F	Report No.:			Is	tation Diary No.:	
08/11/2022								,	
Informant's	Particulars								
Name of Info			Addre	55:					
LIM CHIN FENG									
ID Type / ID No.: NRIC NO			Contact No.: Home/Office: Mobile:						
Nationality:			Email:						
MALAYSIAN			L						
Male	Age: Date 21 ;	of Birth:	Driver						
Race: Chinese			Langu Englis	iage: h		Instituti	on / S	chool Name:	
Occupation:			Driving Class:	g Licence Info	ormation:	Date of	Expir	y:	
General Info	rmation of the	Accident							
Type of	Injury	h. Delies		Drink Drive:	Date/Time Accident:			Type of Location	
Accident:	Attended	by Police		No	08/11/202			Flyover	
Location:									
	EST STREET 8	§1							
JURONG W Weather: Clear	EST STREET 8	31	Road Dry	Surface:			Road	Speed Limit:	
Weather:		31	Dry Traffic	Surface: Control: Light - Work	ing			c Volume:	
Weather: Clear Traffic Flow: Two Way Type of Colli			Dry Traffic	: Control:	ing		Traffi Mode Anyo	c Volume:	
Weather: Clear Traffic Flow: Two Way Type of Colli Between Mo	ision: ving Vehicles -	Head On	Dry Traffic	: Control:	ing		Traffi Mode Anyo ambu	c Volume: rate ne conveyed by	
Weather: Clear Traffic Flow: Two Way Type of Colli Between Mo	ision: wing Vehicles - ehicle involved	Head On	Dry Traffic Traffic	c Control: Light - Work			Traffi Mode Anyo ambu Yes	c Volume: crate ne conveyed by liance:	
Weather: Clear Traffic Flow: Two Way Type of Colli Between Mo Details of V Vehicle No.	ision: wing Vehicles - ehicle involved	Head On	Dry Traffic Traffic	: Control:	ing Color		Traffi Mode Anyo ambu Yes	c Volume: trate ne conveyed by ilance:	
Weather: Clear Traffic Flow: Two Way Type of Colli Between Mo	ision: wing Vehicles - ehicle involved	Head On	Dry Traffic Traffic	c Control: Light - Work		Slig	Traffi Mode Anyo ambu Yes	c Volume: trate ne conveyed by slance:	

Figure 4A: Police Report #1 – Part 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 85470000

Report No. T/20221108/7035

CONTINUATION OF REPORT

Details of Perso	n Involved							
Any Pedestrian Ir	ivolved: No							
No. of Pedestrian	s Injured: NIL		Use of Peo	e of Pedestrian Crossing: NA				
Driver								
Name	Unknown Driver			ID No.		NIL		
Related Vehicle	SHD3095R (Car)			Conta	ct No.	NIL		
Hospital/Clinio	NATIONAL UNIVERS	TAL	Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL			
Date	NIL		Date		NIL			
No. of Days grant	ted Medical Leave	NIL	Degree of		Slight	t		
Driver								
Name	LIM CHIN FENG			ID No.				
Related Vehicle	SHD3095R (Car)			Conta	ct No.			
Hospital/Clinic	NIL			Class Driving Licend Expiry	g e &	Class: NIL Date of Expiry: NIL		
Date	NIL		Date		NIL			
No. of Days grant	ted Medical Leave	NIL	Degree of		NIL			

Brief Details

I am CPL Lim Chin Feng, The Transport operator from Transport Hub West, reporting an incident that occurred today. This is what happened.

On 081122 at about 1038hrs, CPL LIM CHIN FENG was operating a 5-Ton (MID 20935) on Pioneer Road North and turning right into PIE towards Jalan Bahar.

While turning right, a civilian vehicle, SHD3095R was traveling straight in the opposite direction. The 5Ton collided with the civilian vehicle head on.

The civilian is injured and is currently being escorted by SCDF. The Transport operator . Vehicle commander (Captain Jason Foo) and troops are safe.

Darnages to SAF vehicle - front left of vehicle was damaged Darnage to civilian vehicle - Right door and windscreen was damaged

Figure 4B: Police Report #1- Part 2




Figure 4C: Police Report #1- Part 3

	SINGAPORI POLICE FO	RCE					1000	21108/2099
olice Station	Of Origin:						0.75	,
Irong West h	N.P.C on Road SING/	PODERA	ODIO				Repo	at No. (T/2022110
el No: 1800-	2689999	UNICHE 64	a018					- 1
EPORT OF A	TRAFFIC ACCIDE	urr.						
Date/Time R	eport Made		Vide	e Report No.			13	Station Diary N
08/11/2022 1	8:49		T/2	0221108/703	35			52
Informant's								
Name of Info			Audd	ress				
ID Type / ID No				dact No.:				
NRIG NO /				ne/Office:		Mobile	OF SECOND	
Nationality: MALAYSIA	N		Em					
Sex	Age: Date	of Birth:	Typ	e of Informat	nt:			
Male Race:	Male 21			guage:		Institu	tion / S	chool Name:
Chinese				ing Licence				
NSF MAN				85.3.4		Expir	Ø.	
General Info	ormation of the	Accident						
Type of	Injury	by Police		Drink Drive	Date/T Accide			Type of Locati Flyover
Accident: Location:	-			No		2022 10:35	5	M.455044
PIONEER F	ROAD NORTH							
Weather:			Rns	nd Surface:		Road	Speed Limit	
Clear			Dry				and the second second	
Traffic Flow Two Way				ffic Control: ffic Light - Wi	Traffic Volume: Moderate			
Type of Coll			100	7.7			Anyone conveyed by ambulance:	
Between Mo	wing Vehicles - I	nead On					Yes	
	CONTRACTOR CONTRACTOR							
Details of Vi	shicle Involved	Make		Model	- I Cotor	Co	odition	No of Passen
MID20935	SAF 5	7/10/20				Si	phtly	10.
SHD3095R	TONNER Bus/Coach/Mi	HYUNDA	1		Blue		maged riously	
anuauson	nibus (School		W.			Da	maged	<u> </u>
	Children)							
Details of Po	erson Involved							
	an Involved: No			Large	of Pedestr	on Crossi	no NA	

Figure 4D: Police Report #2- Part 1

	GAPORE ICE FORCE			Tr20221108/2099
ice Station Of O ong West N.P.O Corporation Ro No: 1800-2689	pad SINGAPORE 649818			24 Report No. T/20221108/
	CONTI	NUATION OF	REPORT	
river	William Commission		question -	
lame	LIM CHIN FENG		ID No.	
Related Vehicle	MID20935 (SAF 5 TONNER)		Contact No.	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3.4 Date of Expiry: NIL
	N. M.	Date Dis	charge NRL	
Date Treatment	nted Modical Leave NIL	Degree (of Injury Sligh	t6
Name	Unknown	111111111111111111111111111111111111111	ID No.	NIL
Related Vehicle	NIL		Contact No	NIL
Hospital/Clinic	NATIONAL UNIVERSITY HOS	PITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatmen	NO.	Date Di	scharge NIL	
No. of Days gra	inted Medical Leave NIL	Degree	of Injury NIL	
On 8/11/22 at ab North and turning While turning rigi 5Ton collided with The civilian is inju- Commander (Ca	hin Feng, the Transport Operator to bout 1036hrs, CPL Lim Chin Feng gright into PIE towards Jalan Bah ht, a civilian vehicle, SHD 3095R, th the civilian vehicle head on. ured and is currently being escort plain Jason Foo) and troops are	was operation. was travellied by SCOI safe.	ing a 5-Ton (M	(D20935) on Planeer Road ne opposite direction. The
Damages to SAF	Vehicle - front left of vehicle was an vehicle - Right door and wind	s demaged.	damaged.	
Damages to civil	an vehicle - Right door and wird			
Vide incident ren	ort. J/20221108/0094			

Figure 4E: Police Report #2- Part 2




Figure 4F: Police Report #2- Part 3

OFFICIAL (CLOSED) \setminus SENSITIVE NORMAL

WHITE HE STATES	SINGAPO POLICE I	ORCE				ANNOV	INNANA TA	30221 109(2050				
Tel No: 180	ation Road SIN 0-2689999	GAPORE 6	4981	9			R	Japoni Ma. 1/2022				
Date/Time 09/11/2022	Report Made: 2 15:04	DENT		e Report N				Station Diary				
Informent's Particulars				0221108/20	419			105				
Name of Ir LIM CHIN	formant:		Address									
ID Type / I	ID Type / ID No:				Contact No.							
NRIC NO			Home/Office: Mobile									
MALAYSI:			Emak									
Sex	Age: Da	te of Birth		of Informa	nt;							
Male Race:	21	7	Driver Language: Inst				300 I I	School Name:				
Chinese			Driving Licence Information:					reame)				
Occupatio NSF	11			ng Licence s: 3,4	mormaton	Date -	d Екріі	nu:				
Weather:	ROAD NORTH		Road	No Surface	Acciden 08/11/2/	22 10:36		Speed Limit				
Traffic Flor	W1		Dry Treffic Control:					Traffic Volume:				
	Two Way Type of Collision: Between Moving Vehicles - Head On				Not Controlled							
Two Way			_	-	_	-	25000					
Two Way Type of Co Between M	/ehicle Inved		-	Model	Color	Cor	dition	No of Passers				
Two Way Type of Co Between M Details of L Value No.	/ehicle Involved	Maka						10				
Two Way Type of Co Between M Details of L Vehicle No. MI020935	SAF 5							0				
Two Way Type of Co Between M Details of L Value No.	SAF 5 TONNER Bus/Ceach/Mi nibus (School	Muke		AE IONIO HEV 1.8	Blue							
Two Way Type of Co Between M Details of I Value No. MID20935 SHD3005R	SAF 5 TOMNER 8us/Coach/Mi nibus (School Children)	HYUNDAI			Blue							
Two Way Type of Co Between M Details of I Wattigs No. MID20935 SHD3005R	SAF 5 TONNER Bus/Ceach/Mi nibus (School	HYUNDAI		HEV 1.8	Blue							

Figure 4G: Police Report #3- Part 1

PO lice Station Of C	C Toad SINGAPORE 849818	THUATION O	FREPORT	T/20221109/2050 2/ Report No. 3/20221109
HWOR	N. O'D'ALLOWS			
ome	UM CHIN FENG		ID No.	
Related Vehicle	MID20935 (SAF 5 TONNER)		Contact No.	2 10
Hospital/Clinic	NIL			
			Driving Licence & Exply Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL ried Medical Leave NIL	Date Dis	charge Ntt	
Criver		Degree	of Injury NIL	10-10-10-10-10-10-10-10-10-10-10-10-10-1
Name	UNKNOWN		ID No.	NL
Related Vehicle	SHID3096R (Bus/Coach/Min/bu Children)!	is (School	Contact No.	NIL
Hospital/Clinic	NATIONAL UNIVERSITY HOS	PITAL	Class of Driving Licence & Expiry Oate	Class: NIL Date of Expany: NIL
Date Treatment	Nt. nted Medical Leave M.L.		charge ML	
On 68/11/2022 at Florider Road and White lunning right added with V2 ha The univer of V2 is Communitar (Capit	injured and is ourrently being ex- nin Jason Foo) and troops are sa	ng was open to Jalen Bah R, was travel	eting a V1) 5-To sr. ling straight in I	on (WID20935) along the opposite direction. VT
	ont left of vehicle was damaged.			
	whide - Right door and windso	reen was do	maged.	
ON PRODUCT PROCES	J/20221108/0094			

Figure 4H: Police Report #3- Part 2




Figure 4I: Police Report #3- Part 3