



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 42092

ALLIANZ INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD #09-01
SINGAPORE 068897

DATE : 12/11/2022
CLAIM NO. : 12043
POLICY NO. : MC/00950792/01

ATTN: ALLIANZ INSURANCE SINGAPORE PTE. LTD.

FROM : STEPHANIE

VEHICLE NO. : FBR4526E
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	Repair	1.00	\$420.00	420.00
2	BALANCER HANDLE P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$12.00	24.00
3	BEARING 6204 DDU (NSK) P/N: 40237 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
4	BEARING 6301-2NS (NACHI) P/N: 40470 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
5	BEARING 6303 P/N: 29134 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
6	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00
7	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
8	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
9	BOX REAR (YUNMING) ADV47L P/N: 71151 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
10	CLIP COVER (PLASTIC) P/N: 56586 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$6.00	36.00



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
11	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
12	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
13	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
14	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
15	COVER CRANKCASE P/N: 63128 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00
16	COVER SIDE LOWER LH (GREY) P/N: 63488 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
17	COVER SIDE LOWER RH (GREY) P/N: 63490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
18	COVER SIDE REAR LH (GREY) P/N: 63497 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
19	COWLING FRONT LH (GREY) P/N: 63489 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
20	COWLING FRONT RH (GREY) P/N: 63499 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
21	EMBLEM (ABS) P/N: 56578 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	32.00
22	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
23	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	68.00
24	GASKET CLUTCH COVER P/N: 58090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
25	GEAR DRIVE PRIMARY P/N: 62710 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$77.00	77.00
26	GRIP HANDLE LH P/N: 66884 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
27	GRIP HANDLE RH P/N: 67551 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
28	HOUSING CLUTCH P/N: 58135 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
29	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	6.00	\$63.00	378.00
30	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
31	METER IU (12V) NEW MODEL P/N: 34351 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	280.00
32	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
33	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
34	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
35	NUT HOUSING CLUTCH P/N: 64821 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
36	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
37	PLATE CLUTCH FRICTION (AUTO) P/N: 58121 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$119.00	119.00
38	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
39	PROTECTOR EXHAUST P/N: 58086 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
40	SEAL OIL GEAR PRIMARY (21X30X5.5) P/N: 58169 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00
41	SHAFT MAINSTAND P/N: 58180 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00



bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
42	SHAFT PIVOT P/N: 61967 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
43	SHOCK ABSORBER REAR P/N: 58133 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$105.00	210.00
44	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.00
45	STAND SIDE P/N: 58211 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
46	SWING ARM P/N: 58082 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$133.00	133.00
47	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	56.00
48	TYRE 130/70-13 (TIMSUN) TS689 P/N: 65250 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$98.00	98.00

SUB TOTAL	\$2,992.00
GST @ 7 %	\$209.44
GRAND TOTAL (SGD)	\$3,201.44

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



bizSAFE₃



SA1D22BA0005 / Ajax Mars Pte Ltd
 ENTRY DATE & TIME: 10/11/2022 18:58 (SGT)
 SUBMITTED BY: Sabitra
 VERSION: 1 (10/11/2022 18:58 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/11/2022 18:58 (SGT)
Reported by	Driver
Date of Accident	09/11/2022 23:59 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Kaki Bukit rd 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBR4526E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BAN HOCK HIN CO PTE LTD
Company Reg No	1XXXXX288K
Email Address	workshop@bhh.com.sg
Mobile Phone No	(Phone) +65-62816520
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	NMAX155 ABS
Variant	NA
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Manual
CC	155

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MC/00950792

DRIVER

Name of Driver	MURUGAN RAJADURAI
NRIC No	GXXXX538P
Date Of Birth	12/04/1994
Occupation	Outdoor

Date Of Driving Pass	13/05/2019
Driving experience	3 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84523054
Alt. Phone Number	-
Email Address	Muruganraj619@gmail.com
Address	Singapore
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	DRIZZLING
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

WHILE THE TRAFFIC LIGHT JUST TURNED GREEN, I CHECKED MY MIRRORS AND SPOTTED A VEHICLE MOVING QUIET FAST TOWARDS MY DIRECTION FROM THE BACK. SUBSEQUENTLY IT BANGED ME FROM THE BACK CAUSING ME TO FALL AND SKID TOWARDS THE PEDESTRIAN CROSSING AREA . AFTERWHICH WHEN I GAINED BACK MY AWARENESS THE CAR THAT HAD BANGED ONTO ME HAD ALREADY GONE. A FELLOW BYSTANDER THAT HAD WITNESSED THE INCIDENT ASKED ME TO TAKE A PICTURE OF THE VEHICLE (CAR PLATE : SLD7646C, BELIVED TO BE A BLACK IN COLOURED VOLKSWAGEN) THAT HAD BANGED ME . I HAVE YET TO SEE THE HOSPITAL AS I HAVE A COUPLE OF ABRASIONS ON MY BODY.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD7646C
Vehicle Manufacturer	Volkswagen
Vehicle Model	Scirocco
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MURUGAN RAJADURAI
Gender	Male
Phone No	(Phone) +65-84523054
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	FBR4526E
Were seat belts worn?	No
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SHARIL BIN SATAR

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

REFER TO ATTACHED ACCIDENT DIAGRAM

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SHARIL BIN SATAR

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PLEASE SIGN AND DATE HERE

2

ACCIDENT DIAGRAM



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SHARIL BIN SATAR

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**


T20221110/7009

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T20221110/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/11/2022 10:19		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MURUGAN RAJADURAI			Address: 106F AH SOO WALK SINGAPORE 536732		
ID Type / ID No.:			Contact No.:		
FIN NO / G2635538P			Home/Office:		Mobile: 84523054
Nationality: INDIAN			Email: murugnaraj619@gmail.com		
Sex: Male	Age: 28	Date of Birth: 12/04/1994	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 2B, 3C		Date of Expiry: 12/05/2024

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 09/11/2022 23:59	Type of Location: T-Junction
Location: Kaki Bukit Rd 3				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit: 60 Km/h
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of
FBR4526E	Motorcycle	YAMAHA	N MAX	Grey	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No Pedestrians Injured: NIL	
Use of Pedestrian Crossing: NA	

**SINGAPORE
POLICE FORCE**

T/20221110/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000


2 of 3
Report No. T/20221110/7009

CONTINUATION OF REPORT

Rider			
Name	MURUGAN RAJADURAI	ID No.	G2635538P
Related Vehicle	FBR4526E (Motorcycle)	Contact No.	84523054
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 2B,3C Date of Expiry: 12/05/2024
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

While the traffic light just turned green, I checked my mirrors and spotted a vehicle moving quiet fast towards my direction from the back. Subsequently it banged me from the back causing me to fall and skid towards the pedestrian crossing area. After which when I gained back my awareness the car that had banged onto me had already gone. A fellow bystander that had witnessed the incident asked me to take a picture of the vehicle (Car Plate: SLD7646C, Belived to be a black in coloured Volkswagen) that had banged me. I have yet to see the hospital as I have a couple of abrasions on my body.



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65476000

Report No: 1702211107009

CONTINUATION OF REPORT

Sketch Plan
Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/11/2022 10:19
Officer In Charge Of Case: TP / TPJB / FASHIDAH BINTE AZMAN Contact No.: 65476902	Classification Of Case:

This report is lodged at Rochor NPC Kiosk 1
N01150


INSURER ENQUIRY

**Find
insurer**

Vehicle reg. no.

SLD7646C

Date of Accident

09/11/2022 

Reset

% **RESULT & RECEIPT**

TP Insurer Enquiry

Insurance Allianz Insurance Singapore P...

Period of Insurance 11/10/2022 - 10/10/2023

Requested By Gan Lay Peng (Ban Hock Hin C...

Requested Date 11/11/2022 09:18

Payment detailsRequest Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**

Vehicle Details

Vehicle No.	Make / Model
FBR4526E	YAMAHA / NMAX155 ABS

Vehicle Type :

P01 - Passenger Scooter

Vehicle Attachment 1 :

No Attachment

Vehicle Scheme :

Normal

Chassis No. :

MH3SG431000013891

Propellant :

Petrol

Engine No. :

G3H6E0017490

Motor No. :

-

Engine Capacity :

155 cc

Power Rating :

-

Maximum Power Output :

-

Maximum Laden Weight :

295 kg

Unladen Weight :

128 kg

Year Of Manufacture :

2019

Original Registration Date :

01 Jul 2020

Lifespan Expiry Date :

-

COE Category :

D - Motorcycle

Quota Premium :

\$4,489.00

COE Expiry Date :

30 Jun 2030

Road Tax Expiry Date :

31 Dec 2022

PARF Eligibility Expiry Date :

-

Inspection Due Date :

30 Jun 2023

Intended Transfer Date :

11 Nov 2022

CO2 Emission :

CEV/VES Rebate Utilised Amount :