

A.S. REC. BY:

REF:

CS/MSG 22011486/D 94<sup>3</sup>

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

4

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBE 9555G

Yr Regn: 2016 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna 150

c.c. 2982

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 146932

T/Radio: Insured / Std / NI / NA

Eng/No: 1KD2607109

C/No: JTFAT35Y10K206371

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: 155 R12C (Double)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5

mm

R/Bal. 5/5

mm

L/Bal. 5

mm

L/Bal. 5/5

mm

D.O.A. 31/10/2022

D.O.I. 06/12/2022

Survey held at JWG AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG SKO 2099H

22/2/23

prop 2/5 3:5501 - with 4 days of work (Red 49937.53, 93%)

Date/Time, File Pass to?



Prel. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$

Photos

Others

Add Fee: ☐

Site Insp (\$)



Interview (\$)



Tech. Invs (\$)

Report Format: MER-TP

I hereby declare that the above information is true and correct.



# JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 9698 8882 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG

Att: Motor Claims Dept

ACCIDENT INVOLVING SKQ2099H [YOUR INSURED] & GBE9555G [OUR CLIENT]  
ON 31/10/2022.

## ESTIMATED REPAIR COSTS FOR GBE9555G MODEL : TOYOTA DYNA

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	SIDE MIRROR RECTANGLE LH <i>HH</i>	\$ 762.30	X
1PC	SIDE MIRROR ROUND LH <i>HH</i>	\$ 418.70	X
1PC	SIDE MIRROR STAY LH <i>HH</i>	\$ 399.10	X
1PC	SIDE MIRROR GARNISH LH <i>HH</i>	\$ 298.90	X
1PC	FRONT PANEL <i>HH</i> <del>1021.20</del> <i>HH</i>	\$ 1,021.20	X
1PC	FRONT PANEL 'DYNA' EMBLEM <i>HH</i> <del>76.20</del> <i>HH</i>	\$ 76.20	X
1PC	FRONT PANEL SIDE COVER LH <i>Devel</i> <b>276.50</b>	\$ <del>439.00</del>	✓
1PC	WIPER GARNISH LH <i>HH</i>	\$ 412.00	X
1PC	WIPER CENTER BLACK GARNISH <i>HH</i>	\$ 882.00	X
1PC	FRONT GRILLE <i>HH</i> <del>692.00</del> <i>HH</i> <b>561.60</b>	\$ <del>692.00</del>	* ✓
1PC	FRONT GRILLE BASE <i>HH</i>	\$ 711.00	X
1PC	FRONT GRILLE LOGO <i>HH</i> <del>69.00</del> <i>HH</i>	\$ 69.00	* ✓
1PC	HEAD LAMP LH <i>WZK</i> <del>872.70</del> <i>cut</i>	\$ 872.70	✓
1PC	HEAD LAMP WIRE HARNESS <i>HH</i>	\$ 1,142.90	X
1PC	FRONT BUMPER <i>Devel</i>	\$ 692.80	✓
1PC	FRONT BUMPER BEAM <i>HH</i>	\$ 822.10	X
1PC	FRONT BUMPER FOG LAMP GARNISH LH <i>HF</i>	\$ 129.00	X
1PC	FRONT WINDSCREEN MOULDING <i>HH</i>	\$ 295.90	X
1PC	A PILLAR LH <i>HH</i>	\$ 1,249.80	X
1PC	FRONT DOOR LH <i>Devel</i> <b>1568.60</b>	\$ <del>1,789.20</del>	✓
1PC	FRONT DOOR WINDOW MOULDING LOWER LH <i>SH</i>	\$ 198.80	X
1PC	FRONT DOOR WINDOW MOULDING UPPER LH <i>SH</i>	\$ 171.50	X
2PCS	FRONT DOOR HINGE LH @ \$79.00 EACH <i>HH</i>	\$ 158.00	X
1PC	FRONT DOOR INNER TRIM BOARD LH <i>HH</i>	\$ 1,141.90	X
1PC	FRONT DOOR WINDOW MOTOR LH <i>HH</i>	\$ 712.90	X
1PC	FRONT DOOR WINDOW REGULATOR LH <i>HH</i>	\$ 320.40	X
1PC	FRONT DOOR LOCK LH <i>HH</i>	\$ 295.10	X
1PC	FRONT DOOR SPEAKER LH <i>HH</i>	\$ 239.40	X
1PC	FRONT DOOR WEATHER STRIP LH <i>HH</i>	\$ 289.10	X
1PC	FRONT DOOR STEP GARNISH LH <i>HH</i>	\$ 198.20	X



1PC	FRONT WHEEL HOUSING LH HH	\$ 1,890.00	X
1PC	FRONT WHEEL HOUSING TOP GARNISH LH HH	\$ 289.40	X
1PC	FRONT WHEEL HOUSING INNER COWLING LH HH	\$ 301.90	X
1PC	DASHBOARD ASSY HH	\$ 2,893.40	X
1PC	AIRCON BLOWER HH	\$ 2,122.00	X
1PC	AIRCON BLOWER COOLING COIL HH	\$ 1,566.00	X
1PC	AIRCON BLOWER HEATER UNIT HH	\$ 1,654.00	X
2PCS	FRONT RIM LH HH	\$ 853.10	X
2PCS	FRONT WHEEL BEARING LH HH	\$ 239.70	X
2PCS	FRONT WHEEL BEARING HUB LH HH	\$ 342.10	X
2PCS	FRONT KNUCKLE ARM LH HH	\$ 1,045.00	X
2PCS	FRONT LOWER ARM LH HH	\$ 598.10	X
2PCS	FRONT UPPER ARM LH HH	\$ 721.00	X
2PCS	FRONT ABSORBER LH HH	\$ 478.20	X
2PCS	FRONT TIE ROD LH HH	\$ 249.10	X
2PCS	FRONT TIE ROD END LH HH	\$ 289.20	X
2PCS	FRONT STABILIZER LINK LH HH	\$ 198.20	X
1PC	FRONT STABILIZER BAR HH	\$ 629.30	X
1PC	STEERING RACK & PINION ASSY HH	\$ 2,247.10	X
1PC	CENTER PILLAR LH HH	\$ 1,799.20	X
1PC	CENTER PILLAR EMBLEM LH HH	\$ 82.40	X
1PC	FRONT CABIN LOCK ASSY HH	\$ 782.40	X
1PC	FRONT CABIN SAFETY LEVER HH	\$ 219.80	X
1PC	AIR FILTER HOUSING HH	\$ 779.80	X
1PC	REAR DECK HH	\$ 5,098.00	X
1PC	REAR DECK SIDE RUBBER STOPPER LH HH	\$ 84.00	X
1PC	A/C CONDENSOR ASSY HH	\$ 1,302.40	X
1PC	A/C DISCHARGE HOSE HH	\$ 598.20	X
1PC	A/C SUCTION HOSE HH	\$ 692.40	X
1PC	A/C CONDENSOR COWLING HH	\$ 498.20	X
1PC	A/C CONDENSER DRYER RECEIVER HH	\$ 449.00	X
1PC	FRONT CABIN MOUNTING LH HH	\$ 821.00	X
1PC	FRONT CABIN MOUNTING BEAM HH	\$ 1,562.00	X

4041.20  
3,030.90  
5

PARTS SUM: \$ 50,276.70  
PARTS LESS 25%: \$ 12,569.18  
PARTS TOTAL: \$ 37,707.53

### LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT LH 1PCS TYRE HH	\$ 600.00	X
*	TO SUPPLY FRONT DOOR COMPANY STICKER CL	\$ <del>50.00</del>	201r
*	TO SUPPLY FRONT WINDSCREEN SEALANT HH	\$ 80.00	X
*	TO SUPPLY FRONT WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY FRONT WINDSCREEN INNER SEAL HH	\$ 50.00	X

*	TO SUPPLY FRONT PANEL SEALANT HH	\$ 50.00 X
*	TO SUPPLY FRONT GRILLE CLIPS HH	\$ 50.00 X
*	TO SUPPLY HEAD LAMP CLIPS HH	\$ 50.00 X
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS HH	\$ 50.00 X
*	TO SUPPLY DASHBOARD ASSY CLIPS HH	\$ 50.00 X
		20.00 =
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ <del>6,000.00</del> 700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ <del>6,000.00</del> 600/-
*	TO TUFF COAT DAMAGED AREAS	\$ <del>300.00</del> 20/-
*	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	\$ 200.00 HH
*	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	\$ 150.00 HH
		1400.00 =
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00 HH
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00 HH
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ <del>250.00</del> 60/-
*	TO RNR REAR DECK TO FACILITATE REPAIRS	\$ 800.00 HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ <del>200.00</del> 20/-

**LABOUR & S/N TOTAL: \$ 15,780.00**

**GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 53,487.53**

06/12/2022 @ 10:15h  
N/A Auto

4450-90  
4/5 3,550/-

2/3m 4 days.  
Tiger  
2XK sub  
[Signature]

Check Part prices.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	904J
<b>Vehicle Details</b>	
Vehicle No.:	GBE9555G
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2607109
Chassis No.:	JTFAT35Y10K206371
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	11 May 2016
First Registration Date:	11 May 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$16,206.00
<b>Total Rebate Amount:</b>	<b>\$16,206.00</b>

The information contained herein is correct as at 15 Nov 2022

OK

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Elantra 1.6A, 100% Loan by GV CARS FINANCING



Secured Loan by In house  
finance, Warranty packages and  
services available.  
GV Automobile Centre StarAd



Sort by  20 results/page

20 vehicles



toyota dyna

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	toyota dyna		Any	Any	2016	Any	Any	Any	Available
	Toyota Dyna	150 3.0M	\$50,800	\$13,480 /yr	23-Aug-2016	2,982 cc	129,786 km	Truck	Available
	<b>Fuel Type:</b> Diesel Best 10 feet box up lorry in market, low mileage! Smooth Engine & Gearbox! 100% accident free! Free servicing and warranty are provid... ABS Bus Pte Ltd Posted: 14-Nov-2022								PREMIUM AD
	Toyota Dyna	150 3.0M	\$53,800	\$14,870 /yr	29-Jun-2016	2,982 cc	-	Truck	Available
	<b>Fuel Type:</b> Diesel 1 OWNER WITH GENUINE LOW MILEAGE CLOCKED! New Paintwork & Upholstery done. Exclusive warranty and servicing package Includ... Car (S) Pte Ltd Posted: 14-Nov-2022								PREMIUM AD
	Toyota Dyna	150 3.0M	\$64,888	\$17,440 /yr	05-Aug-2016	2,982 cc	-	Truck	Available
	<b>Fuel Type:</b> Diesel Well maintained Toyota Dyna 150 with freezer box attachment. Powerful 3.0L engine with smooth manual transmission. Fast and big coo... Posted: 14-Nov-2022								
	Toyota Dyna	150 3.0M	\$53,800	\$13,960 /yr	23-Sep-2016	2,982 cc	-	Truck	Available
	<b>Fuel Type:</b> Diesel 10ft G Plate Toyota Dyna. Excellent Condition And Come With Full Canopy. Perfect for transport workers or goods. 100% In House Loan... ABWIN (1994) Pte Ltd Posted: 12-Nov-2022								
	<b>VVTi Toyota / Nissan Red I Stick-On Car Emblem</b> VVTi with Red i More info about this product								
	Toyota Dyna	150 3.0M	\$53,800	\$15,620 /yr	26-Apr-2016	2,982 cc	-	Truck	Available
	<b>Fuel Type:</b> Diesel 1 ownership with genuine low mileage! Premium 3 months warranty with further lucrative packages! High loan options with the lowest d... Car (S) Pte Ltd Posted: 11-Nov-2022								PREMIUM AD
	Toyota Dyna	150 3.0M	\$56,800	\$14,070 /yr	29-Nov-2016	2,982 cc	99,800 km	Truck	Available
	<b>Fuel Type:</b> Diesel Exclusive premium warranty provided. Unit equipped with 7 feet box with easy access from both side and rear. Genuine low mileage don... Car (S) Pte Ltd Posted: 11-Nov-2022								PREMIUM AD
	Toyota Dyna	150 3.0M	\$51,800	\$13,820 /yr	15-Aug-2016	2,982 cc	124,507 km	Truck	Available
	<b>Fuel Type:</b> Diesel								PREMIUM AD

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	11/11/2022 21:49 (SGT)
Reported by	Driver
Date of Accident	31/10/2022 09:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ADMIRALTY ROAD WEST
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE9555G
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	EASTSIDE ELETRICAL SERVICE
Company Reg No	52951904j
Email Address	eastside_elect@yahoo.com.sg
Mobile Phone No	(Phone) +65-96719484
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

#### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5127317529

#### DRIVER

Name of Driver	VELLAISAMY MURUGESAN
Passport No/FIN	G8557718U
Date Of Birth	13/08/1996
Occupation	Outdoor



Date Of Driving Pass .....	06/08/2021
Driving experience .....	1 YEAR AND 2 MONTHS
Gender .....	Male
Mobile Number .....	(Phone) +65-89347015
Alt. Phone Number .....	-
Email Address .....	eastside_elect@yahoo.com.sg
Address .....	C/O 15 JALAN KEMUNING SEMBAWANG SPRINGS ESTATE
Address complement .....	-
Postcode .....	769737
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Employee
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	3
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	Yes
Police Station Name .....	Sembawang Neighbourhood Police Centre
Police Station Phone No .....	(Phone) +65-18005549999
Police Station Address .....	4 Sembawang Crescent Singapore 757633
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO POLICE REPORT

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SKQ2099H
Vehicle Manufacturer .....	Toyota
Vehicle Model .....	Previa
Vehicle Variant .....	-
Vehicle Colour .....	-



Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YP7097U
Vehicle Manufacturer	Isuzu
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

GBE 9555G (Aniome)  
DPA: 31/10/22 @ 0930

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



*Sulman*

*V. Deen A. 11/11/2022*



Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

**Sulaiman Mohamed Kuti**  
VC 101/B

SP Group Sub Station  
Gate



A: GBE 9555G

B: SKQ2099H

C: YP7097H



Describe Circumstances of the Accident

Refer to Police Report NO: T/20221107/2055.

I will be claiming my vehicle at C.S. ONG AUTO PTE LTD.

Declaration

We declare the foregoing particulars are true in every respect.



*Sulaiman*

Policyholder's Signature / Date & Time

**Sulaiman Mohamed Kuti**  
VC 101/B

*V. M. M. M.*

Driver's Signature (If driver is not the policyholder) / Date & Time

*(Signature)*

Witnessed by Reporting Centre Personnel

## EASTSIDE ELECTRICAL SERVICE

Co. Reg. No.: 52951904J  
15 JALAN KEMUNING SEMBAWANG SPRINGS ESTATE S (769737)  
Office: 9671 9484  
E-Mail: eastside\_elect@yahoo.com.sg

### LETTER OF AUTHORISATION

11-Nov-2022

To: Accident Reporting Centre (ARC)


I / We hereby approved Vellaisamy Murugesan Fin G8557718U,  
our employee of Dipcie Contractors Pte Ltd to drive our  
vehicle no. GBE9555G and to file the accident report  
which occurred on 31/10/2022 at 0930hrs along Admiralty Road West.

\* Relationship: Employee of Dipcie Contractors Pte Ltd (vehicle of Eastside Electrical Services Pte Ltd broke down hence I am using the other company vehicle which I owned).

Thank you.

Regards,

Sulaiman Mohamed Kuti  
UC 101/B



Name of Owner: Eastside Electrical Service  
UEN: 52951904J  
Contact No: 9671 9484








































**SINGAPORE  
POLICE FORCE**



T/20221107/2055

1 of 3

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

Report No. T/20221107/2055

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 07/11/2022 13:59	Vide Report No.: L/20221031/0051	Station Diary No.: 59
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: VELLAISAMY MURUGESAN	Address:	
ID Type / ID No.: FIN NO / G8557718U	Contact No.: Home/Office: Mobile: 89347015	
Nationality: INDIAN	Email:	
Sex: Male Age: 26 Date of Birth: 13/08/1996	Type of Informant: Driver	
Race: Indian	Language:	Institution / School Name:
Occupation: CONSTRUCTION WORKER	Driving Licence Information: Class: 2B,3 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 31/10/2022 09:30	Type of Location:
Location:  ADMIRALTY ROAD WEST				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow:	Traffic Control:	Traffic Volume: Light		
Type of Collision: Moving Vehicle Against - Parked Vehicle		Anyone conveyed by ambulance: Yes		

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE9555G	Lorry	TOYOTA	DYNA	Grey	Slightly Damaged	1
SKQ2099H	Car	TOYOTA	PREVIA	Silver	Seriously Damaged	1
YP7097U	Lorry	ISUZU		Blue	Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20221107/2055

2 of 3

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

Report No. T/20221107/2055

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	VELLAISAMY MURUGESAN		ID No. G8557718U
Related Vehicle	GBE9555G (Lorry)		Contact No. 89347015
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	LIM KIM SENG		ID No. S1419322G
Related Vehicle	SKQ2099H (Car)		Contact No. 96776672
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On 31/10/2022 at about 0930hrs, I had parked my vehicle GBE9555G in front of Admiralty Road West 230kv as I was supposed to do some electrical works in the said location. I had parked on the right side in front of the gate while on the left side of me was YP7097U. Both our vehicles are stationary and our engines are off. Driver of SKQ2099H parked his vehicle directly behind YP7097U and had gotten off his vehicle. I remembered I was inside the lorry and saw driver of SKQ2099H coming out of his vehicle. Suddenly, his vehicle SKQ2099H started to move off and hit the left side of my vehicle causing scratches and went straight into lorry YP7097U. The entire bumper of SKQ2099H came off from its vehicle.

The driver got hit on his right leg due to the accident and was conveyed by ambulance.





SINGAPORE  
POLICE FORCE



T/20221107/2055

3 of 3

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

Report No. T/20221107/2055

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

L /  
SGT 3 NUR ATIQA BINTI  
ABDULLAH @ ABDULL RAHIM

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
07/11/2022 13:59

Officer In Charge Of Case:  
TP / GIT /  
SR STAFF SGT MUHAMMAD AFIQ BIN  
JOHARI  
Contact No.: 93840429

Classification Of Case:

NP168