

(98/11/22)

ASS. REC. BY:

REF:

CS3/INC22011500/Sny3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. MT/1196858-001

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

01/12/22 submit PRS

Date/Time, File Pass to?

1) 01/12/22

Date/Time, File Return to?

2)

Report Format:

PRS

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

\$ = RS. \$

Photos

Others

TOTAL

Veh No:

SKM2332E

Yr Regn:

22 Feb 2017

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

mercedes A200

c.c 1569

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

90512

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD1760432J503819

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim; or

Tyre Size:

F:

225/40 R18

R:

225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/11/22

D.O.I.

16/11/22 11am

Survey held at

garage 13

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Balance: \$1m

yearly: 17K

mv: 83K

NV: 45K

Preli. Report

Final Report

1) 01/12/22

Date/Time, File Return to?

2)

Report Format:

PRS

Lump Sum / I.B.I. (\$)