



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: AZHARI AFIDI

Ref: CS/INC22011502/Aqy3m4

Date: 24/02/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 6316S	Veh. Inspected	SLX 7756M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1196985-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/11/2022

2. Vehicle Particulars & Condition

Make & Model	KIA CARENS	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAHU815VJ7203796	Colour	RED
Odometer	223978 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	KAPSEN	6 mm
L/H Front Tyre	225/45 R17	KAPSEN	6 mm
R/H Rear Tyre	225/45 R17	KAPSEN	6 mm
L/H Rear Tyre	225/45 R17	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/11/2022	Inspect Date / Time	16/11/2022 (04:02 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**