

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | |
|---------------------------|--|------------------------|---------------------|-------------------------|--|
| | INCOME INSURANCE LTD | | Ref: | CS/INC22011504/Aqy3e2 | |
| | 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 | | Date: | 20/03/2023 | |
| | ATTN: ENG HUEY | HUEY | Code | : INC | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBJ 1772Y | Veh. Inspected | GBK 7566G | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | MT/1196967-002 | Excess (\$) | 0.00 | |
| | Assign From | HAZALYSA BINTE IBRAHIM | Assign Date | 16/11/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | NISSAN NV200 | c.c | 1597 | |
| | Engine No. | HIDDEN | Year of Reg. | 2020 | |
| | Chassis No. | VM20161646 | Colour | BLACK | |
| | Odometer | 96875 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | NIL | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 185/65 R14 | YOKOHAMA | 6 mm | |
| | L/H Front Tyre | 185/65 R14 | YOKOHAMA | 6 mm | |
| | R/H Rear Tyre | 185/65 R14 | YOKOHAMA | 6 mm | |
| | L/H Rear Tyre | 185/65 R14 | YOKOHAMA | 6 mm | |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | 5. General Information | | | | |
| | Accident Date | 14/11/2022 | Inspect Date / Time | 16/11/2022 (03:28 PM) | |
| | Survey held at KT MOTORWERK | | | | |
| | 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 | | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | 12 Wo | orking Days | |
| | | | | | |