

References

Smy9261T. Yr Recn: 2021 / March

Veh No: 011712611 Yr Regn: 8021 / March.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yoyota Alpherd. C.C. 2493

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 56223 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AYH 300097347.

Gen. Cond: Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/30R18

R: 235/55R18.

	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Habilead

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 17/4/22

Survey held at HD Perfect. 1

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Len Pac.
	MV :
	PV :
	Nett :
	452D

☐: Prel. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Forest Forest :

RECEIVED: 1977 FEB 15

Add Fee: ☐ : Site Insp (4)

Interview (\$)

: Tech. 1992

Photos

11 Officers