

ASS. REC. BY: Marcus

REF:

CS/LPC 22011535/U943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

\$ 70k.

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

C 54812

LTA 18956

Dep 1 Mc
10e ant. 1 30-06-2028

Veh No:

PA9085B

Yr Regn:

06/08/09

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

1500cc L7134P

c.c 7790

Colour

White / Blue

A/C: Insured / Std / NI / NA

Sp. Reading

479612

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JALLT134P.87000171

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 295 / 80 R22.5

R:

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

18/09/22

D.O.I.

15/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) __ \$ + RS. __ \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	548K
Vehicle Details	
Vehicle No.:	PA9085D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2022
Vehicle Make:	ISUZU
Vehicle Model:	LT134P
Primary Colour:	Multicolor
Manufacturing Year:	2008
Engine No.:	6HK1472754
Chassis No.:	JAI.LT134P87000171
Maximum Power Output:	-
Open Market Value:	\$101,094.00
Original Registration Date:	06 Aug 2009
First Registration Date:	06 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$5,055.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$33,717.00
COE Rebate Amount:	\$18,956.00
Total Rebate Amount:	\$18,956.00

The information contained herein is correct as at 16 Nov 2022

OK