

Your Ref: S1M03N56

Date: 14th Dec 2022

Our Ref: CS3/ASM21012139/Cqp3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMS 575D

INSURED VEHICLE: SH 7265P

ACCIDENT DATE: 27/11/2021

We thank you for your instruction on 11/11/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMS 575D from M/s PAR Automobile Consultancy.
- b) Singapore Accident Statement of Vehicles SMS 575D and SH 7265P.
- c) Police Report of Vehicles SMS 575D.
- d) Final Repair Bill of SMS 575D from M/s Hiap Lek Automobile Trading.
- e) Colour damaged vehicle photographs of SMS 575D.

Pre-Repair Inspection Date: 30/11/2021 at M/s 160 Sin Ming Drive #05-07, Repairer: Hiap Lek Automotive Trading.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMS 575D
Make & Model	: Mercedes Benz E200 AVG Auto
Year of Registration	: 2017
Chassis Number	: WDD2130422A120788
Engine Capacity	: 1991 cc

2. We recommend that the repairs of the entire damage require about 13 (Thirteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.