

ADVANCE AUTO GARAGE

VEHICLE DETAILS

VEHICLE NO : SLW5889G 2018 JAN
 VEHICLE MODEL : VOLKSWAGEN PASSAT
 CHASSIS NO : WVVZZZ3CZJE099220

TP MS16
 Venn

ACCIDENT DETAILS :
 DATE :
 TIME :

THIRD PARTY REQUESTOR / CONTACT : XAIVER / 90079247

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR WING MIRROR <i>eng</i>	1	\$ 859.00	\$ 859.00
2	FRONT DOOR WING MIRROR COVER <i>cut d</i>	1	\$ 105.00	\$ 105.00
3	FRONT DOOR WING MIRROR GLASS <i>new</i>	1	\$ 398.00	\$ 398.00
4	FRONT DOOR WING MIRROR SIGNAL LAMP <i>new</i>	1	\$ 198.00	\$ 198.00

TOTAL PRICE: \$ 1,560.00
 LESS 10% \$ 156.00
 SUB TOTAL PRICE: \$ 1,404.00

964
 867.60

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 200.00	100	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 200.00	100	
3	WIRING CHECK	\$ 50.00	30	

TOTAL: \$ 450.00

230

ESTIMATE REPORT

TOTAL PARTS COST: \$ 1,045.80
 TOTAL LABOUR COST: \$ 450.00
 TOTAL REPAIR COST: \$ 1,495.80

Total: 1097.60

4/5: 800

01 Day

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: