

4.4.

From: _____ Date: _____

Veh No: YQ69724. Yr Regn: 2022 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2755

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 11315 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHHAGV4610K002546

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/75 R15

R: 145/80R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO OF

Front Rear

R/Bal. 00 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 18/11/22

Survey held at Ferry Motel

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

3054.

: Prel. Report

Final Report

Days Of Repair: -

Resurvey No. of Trip:

Survey Fee:

Transportation:

Acid Fee: : Site Insp (\$

3 + RS, SI

Interview (\$)

Photos

: Tech. Inv. (2)

Others

Figure 1. *Figure 1*

[illegible]