

REF:

ASSIGNMENT

Veh No: SKU829 Yr Regn: 2011 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Passat C.C. 1178

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 48736 , T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VVW 2223 C 2KE1 21443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

*Survey held at 8M

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

The U/C / Chassis frame / Body Structure affected due to collision.

Nett:

☐: Prelim. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Transportation:

Add Fee: : Site Insp (1)

1: Interview (3)

Test 1000

$S \div RS = S$

Photos

Others