

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN		Ref:	CS3/SMO22011659/Uny3e2		
	50 RAFFLES PLAC SINGAPORE LAND	E #03-03 O TOWERSINGAPORE 048623		Date:	28/12/2022	
				Code:	SMO	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJT 9478Y	Veh. Inspected	i	SBG 8831E	
	Policy No.	D22MTPV01016721	Coverage (\$)		0.00	
	Claim No.	CMTD2204107/GPL	Excess (\$)		0.00	
	Assign From	MELVIN YE	Assign Date		21/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ 200E (A)	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		1989	
	Chassis No.	WDB1240212A892573	Colour		WHITE	
	Odometer	384242 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	MICHELIN		6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN		6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN		6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
5.	General Information					
	Accident Date	10/11/2022	Inspect Date /	Time	08/12/2022 (12:47 PM)	
	Survey held at ORION AUTOCLINIC PTE LTD					
	NO. 25 KAKI BUKIT ROAD 4 #03-31 SYNERGY@KB SINGAPORE 417800					
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/SMO22011659/Uny3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser