



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011670/Uqy3q2	
			Date: 15/05/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMG 6160R	Veh. Inspected	SKW 2155Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203940/RUC	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	21/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN JETTA (A)	c.c	1390
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WVWZZZ16ZFM029940	Colour	SILVER
	Odometer	194794 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	GOODYEAR	6 mm
	L/H Front Tyre	225/40 R18	GOODYEAR	6 mm
	R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
	L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2022	Inspection Date	23/11/2022
	Survey held at	FC AUTO GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4, #04-03, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	