

AE.S. REC:BY: T. G. J. M.

REF: CS/CT/2201/671/Trp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 975K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GW9982C

Yr Regn: 2022 Aug

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350

c.c. 1998

Colour: Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: 6781

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN/MIA 2E2 6Z 0000308

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/80 R15

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 21/11/22 21250

Survey held at By post

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. invs (\$ _____)

☐

: Weeding (\$ _____)

S + RS \$ _____

Photos _____

Others _____

Rep. Form: _____

Lum Sum / L.B. / P. _____

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: GW9982C

Make & Model: Nissan NV350

Chassis number: JN1MA2E26Z0000308

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ <i>bt</i> 1,816.17
2	Tailgate windscreen glass rubber moulding	1	\$ <i>net</i> 61.20
3	Tailgate "NV350" emblem	1	\$ <i>net</i> 101.30
4	Tailgate "Urvan" emblem	1	\$ <i>net</i> 69.70
5	Tailgate centre emblem	1	\$ <i>net</i> 64.80
6	Tailgate chrome moulding	1	\$ <i>X</i> 535.70
7	Tailgate RH number plate lamp	1	\$ <i>X</i> 55.60
8	Tailgate LH number plate lamp	1	\$ <i>X</i> 55.60
9	Tailgate open handle	1	\$ <i>X</i> 163.00
10	Tailgate lock	1	\$ <i>bt</i> 271.30
11	Tailgate lock cover	1	\$ <i>X</i> 37.30
12	Tailgate lock catch	1	\$ <i>X</i> 35.10
13	Tailgate central lock device	1	\$ <i>X</i> 200.90
14	Tailgate RH hinge	1	\$ <i>X</i> 55.60
15	Tailgate LH hinge	1	\$ <i>X</i> 55.60
16	Tailgate RH absorber stay	1	\$ <i>X</i> 199.30
17	Tailgate LH absorber stay	1	\$ <i>X</i> 199.30
18	Tailgate inner trim board	1	\$ <i>X</i> 202.20
19	Tailgate weatherstrip	1	\$ <i>net</i> 162.30
20	Rear bumper	1	\$ <i>bt</i> 677.40
21	Rear bumper RH side retainer	1	\$ <i>X</i> 22.30
22	Rear bumper LH side retainer	1	\$ <i>X</i> 22.30
23	Rear bumper centre step panel	1	\$ <i>bt</i> 169.70
24	RH taillamp assy	1	\$ <i>X</i> 288.40
25	RH taillamp panel	1	\$ <i>X</i> 117.80
26	LH taillamp assy	1	\$ <i>X</i> 288.40
27	LH taillamp panel	1	\$ <i>X</i> 117.80
28	End panel (inner) <i>outer</i>	1	\$ <i>bt</i> 461.80
29	Floor panel end plate moulding	1	\$ <i>bt</i> 75.80
30	Floor panel top trim carpet	1	\$ <i>X</i> 587.00
31	Exhaust silencer	1	\$ <i>X</i> 708.00
32	Exhaust silencer gasket	1	\$ <i>X</i> 36.00

\$ 7,914.67

Parts less 10% \$ 791.47

Total \$ 7,123.20

VEHICLE NO: 6W 9987 C

MAKE & MODEL: NISSAN

AUTO/MANUAL

DATE OF ACCIDENT	17 / 11 / 2022	CC 2-0
TIME OF ACCIDENT	3:00 AM / PM	
LOCATION OF ACCIDENT	LENTOR AVE towards YISHUN AVE 2 before YISHUN AVE	
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE	
NAME OF OWNER	99 frontiers pte ltd	
EMAIL	admin@99frontiers.com	OFFICE: MOBILE: 8334 0253
NRIC	202133048N	
CLAIM TYPE	OD / THIRTY PARTY / REPORTING ONLY	
FLEET POLICY	YES / NO?	
INCURANCE CO.	NTUC	
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO.	5129730584	
NAME OF DRIVER	AS ABOVE / IF NO: Tan hai Jie	
NRIC	S8431290h	
DATE OF BIRTH	30 / 09 / 1984	
ANY PASSENGER	YES / NO	
NAME OF PASSENGER		
GENDER OF PASSENGER	MALE / FEMALE	
OCCUPATION	Outdoor / Indoor	
DATE OF DRIVING PASS	15 / 12 / 2004	
GENDER	MALE / FEMALE	
CONTACT NO.	Mobile: 8334 0253 Office: Home:	
EMAIL	tanhaijie84@gmail.com	
ADDRESS	15 canberra drive #12-29	
DOES DRIVER OWN OTHER VEHICLES?	NO / If yes, Reg No: INSURE:	
RELATIONSHIP	Employee / If No:	
WEATHER CONDITION	Clear / Raining / Other:	
ROAD SURFACE	Dry / Wet / Other:	
ANY INJURIES	No / If yes, Who?	
CONTACT NO.		
ROLICE REPORT	No / If yes, Where?	
NOTICE OF INTENDED PROSECUTION?	No / If yes, Who?	
VEHICLE B NO.	SJW 4466 Z Any Passenger:	
NAME		
CONTACT NO.		
VEHICLE C NO.	Any Passenger:	
VEHICLE D NO.	Any Passenger:	
VEHICLE E NO.	Any Passenger:	
VEHICLE F NO.	Any Passenger:	
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	YES / NO	
WAS THERE ANY AUDIO RECORDED?	YES / NO	
SCENE ACCIDENT PHOTOS TAKEN?	YES / NO	
WHO IS REPORTING	DRIVER / OWNER / BOTH	
Original Language Used	English / Mandarin / Others:	
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?	YES / NO	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

I was stationary along LENTON AVE towards YISHOW AVE
I before YISHOW AVE I waiting for the traffic light to
turn green. Suddenly, I felt a huge impact coming from
the rear of my vehicle A. I got out realise vehicle B
knock onto me.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

MV: \$75K.

ce: 1998

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	048N

Vehicle Details

Vehicle No.:	GW9982C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Nov 2022
Vehicle Make:	NISSAN
Vehicle Model:	NV350 URVAN PANEL VAN 5AT
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	QR20019940R
Chassis No.:	JN1MA2E26Z0000308
Maximum Power Output:	-
Open Market Value:	\$22,788.00
Original Registration Date:	25 Aug 2022
First Registration Date:	25 Aug 2022
Transfer Count:	0
Actual ARF Paid:	\$1,140.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	24 Aug 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$46,193.00
COE Rebate Amount:	\$36,954.00
Total Rebate Amount:	\$36,954.00

The information contained herein is correct as at 18 Nov 2022

OK