


ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD ☒ TP / VS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: GBL 8824A
Policy No. DMCVSNW00079542200
Claims No. SNM22D207905/C02/IRENE
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SJW 879Z Yr Regn: 2009 April
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mercedes Benz C200 C.C. 1796
Colour: Beige A/C: Insured / Std / NI / NA
Sp. Reading: 69540 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD 2040417A 245281
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / ☒ S/Rim / STD A/Rim or
Tyre Size: F: 275/45 R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: R/Bal. 6 mm L/Bal. 6 mm
Rear: R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 1/11/2022 D.O.I. 21/11/27
Survey held at AT Performance.
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction
	Repair Range: \$3500 - \$4500, 5 days.
22/11/22	Submit PRS, repair range \$3500-\$4500

Date/Time, File Pass to? ☐ : Prel. Report ☐ : Final Report
Date/Time, File Return to? 2) 22/11/22-typist
Days Of Repair: 5
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. invs (\$) ☐ : Weighing (\$) ☐ : S + RS \$1. ☐ : Photos ☐ : Others
Repair Form: _____
Lump Sum / E.B. / P. _____
https://singapore.marimen.com/claims/index.cfm?fusebox=MTRrepairer&fuseaction=dsp_clmheader&caseid=1101882&CFID=95134052&CFTOK...



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/11/2022 16:49 (SGT)
Reported by	Both
Date of Accident	01/11/2022 16:10 (SGT)
Exact Location of Accident	Kallang Rd & Padang Jeringau, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ879Z
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Ng Chu Teck
NRIC No	S0036708G
Email Address	ctng_sg@yahoo.com.sg
Mobile Phone No	(Phone) +65-98345534
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	C200k
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1796

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100133423-13

DRIVER

Name of Driver	Ng Chu Teck
NRIC No	S0036708G
Date Of Birth	15/08/1948
Occupation	Indoor

Date Of Driving Pass	04/06/1969
Driving experience	53 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98345534
Alt. Phone Number	-
Email Address	ctng_sg@yahoo.com.sg
Address	38 Gilstead Road #01-04
Address complement	-
Postcode	309080
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	GBL8824A
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

enc
in.

day

%

R

o

ci

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Signature]

Policyholder's Signature / Date & Time
2/11/2022
Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card) **SOH JIT HOON**



Describe Circumstance of the Accident

MY CAR WAS STATIONARY ON THE THIRD LANE DUE TO TRAFFIC
LIGHT WAS RED.
MOMENTS LATER, A VAN GBL 8824A CAME FROM BEHIND AND
HIT INTO MY CAR REAR SECTION.

(We declare the foregoing particulars are true in every respect.)

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card) SOH JIT HOON