OB/11/13) Wef REF: CS/F	Cl22011698/Rny3
	ASSIGNMENT
From: Date:	Veh No: SLU 362C Yr Regn: 2017 NOV
Estimated Cost:	Type://ii.Car/ M.Cycle/Bus/Van/Lorry/Taxi/Prime Mover/
OD/TP/WS/TP RES/OD RES/EVA/INV/IMV	Truck Trailer or
To Inspect Vehicle No: SLW 362C	Make: TOYOTA PRIMSHYBELO 18 c.c 1798
at Workshop m/s Borne proton	Colour CROY A/C: Insured / Std / NI / NA
of Pansan Crescent	Sp.Reading 435760 T/Radio: Insured Std / NI / NA
Insured: FC(Eng/No:
Policy No.	C/No: JTP KB3FU003576006
Claims No.	Gen. Cond: Good Fairl Poor Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: horder Jammed Leaked Burnt or
Make of Veh:	Modi: NII 7 STED A/Rim or
* :	Tyre Size: F: 198 65RUS
(Policy Condition)	R: "A.
Remark: The veh had commenced its N/S	O/S BS (DUN/ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM!)
repair at the time of inspection.	TOYO1YOKO or
Bal. or Market Value: 92K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 4 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	1/Bai. 6 mm L/Bat. 6 mm
Est. Repairs: 3 days Res.: Yes or No	D.O.A. 17 11/2 D.O.I. 1811/22
Lum Sum: % 3 Val.: Yes or No	Survey held at harped room
	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: 1N	als Ocas
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
REPAIR LINA - SOK	
	*
subject to their energy of	al a cost of repair P/P \$3,699.20 /- with 03 days of repair,
(red	, \$5670.40, 61%)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
T. Final Danast	Resurvey No. of Trip: 1 Survey Fee:
) 16/12/22 : Final Report	
) 16/12/22 Final Report Date/Time, File Return to?	Transportation:
Date/Time, File Return to?	Transportation: Site Insp (\$)S+RSS
Date/Time, File Return to?	