



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22011720/Any3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 30/01/2023

ATTN: CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNE 5102P	Veh. Inspected	SMD 671M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1197663-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	22/11/2022

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	999
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WVWZZZAUZJW278890	Colour	ORANGE
Odometer	33308 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	ROTALLA	6 mm
L/H Front Tyre	205/55 R16	ROTALLA	6 mm
R/H Rear Tyre	205/55 R16	ROTALLA	6 mm
L/H Rear Tyre	205/55 R16	ROTALLA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/11/2022	Inspect Date / Time	22/11/2022 (04:39 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------