

 Service Request Details

Claim	S2M04F4J
Reference	CS3/ASM22011721/Tnp3m4 
Loss Date	17 November 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	18 Nov 2022 3:31:54 PM
Request Date	22 November 2022
Due Date	

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SLK5836Y
Vehicle	
Registration #	
Make	TPVD- Chevrolet
Model	ORLANDO 1.4AT TURBO

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2207756.pdf	Email Sent	Surveyor/	LKK AUTO CONSULTANTS	16 December

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
		Assessor expense	PTE LTD (TP)	2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2022
 AXA Immediate Advice - SLK5836Y (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 December 2022
 EMAIL FROM SOLICITOR.msg.msg	Letters and Correspondence	Solicitor / Advocate	PODUVAL Akash	22 November 2022
 TP PRI.msg.msg	Letters and Correspondence	Workshop	PODUVAL Akash	22 November 2022
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL Akash	22 November 2022
 TP GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	22 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 INSD GIA REPORT -SHA2253Z.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	22 November 2022
 SJ0G22BI000A-SHA2253Z.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	18 November 2022