

ASS. REC. BY:

REF:

C724

CS/CTI22011736/Kqp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 4876E

Yr Regn:

05, 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour

M. Black

AC:

Insured / Std / NI / NA

Sp. Reading

140832

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU 3 - 1120517

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

J

mm

Rear

R/Bal.

J

mm

L/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

18/11/22

D.O.I.

22/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassals frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Kenneth finalised LS \$3200, 4 days (Red \$10230.42, 76%)

Date/Time, File Pass to?



: Prell. Report



: Final Report

1) 11/04 Typist

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

TOTAL

Report Format:

MER-TP

Lump Sum H.B. (\$) 3200

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

Not Authorised
11/11/22
Penny After Penny
8-5days

ESTIMATE

LOH HWEE PENG PATRICIA
C/O 46 LENTOR PLAIN
SINGAPORE 786548

Date : 22/11/2022

QUANTITY	PARTICULARS	AMT (\$)
RE : HONDA VEZEL / SLC 4876 E		
1pc	rear bumper center pad	897.62 ✓
2 pcs	rear bumper side pad <i>n/s max o/s ?</i>	866.40 ✓
16 pcs	rear bumper clip	51.20 ✓
2 pcs	rear bumper side retainer	157.80 X
2 pcs	rear bumper reflector	592.80 X
1pc	rear bumper lower dust cover	422.10 X
1pc	rear end outer panel	863.74 ?
1pc	rear end inner sub panel	552.30 X
1pc	rear end panel trim	363.20 ?
1 pc	rear remote lock buzzer	265.40 X
1pc	rear remote lock sensor	314.80 X
1pc	rear tail door lock catch	84.60 X
1 pc	rear tail door emblem "VEZEL"	67.50 ✓
1pc	rear tail door emblem "LOGO"	62.80 X
1pc	rear tail door weatherstrip	369.51 X
1pc	rear tail door glass moulding	269.40 ✓
1pc	rear tail door outer garnish	598.74 X
2 pcs	rear tail door lamp	1,197.20 X
2 pcs	rear tail lamp	1,096.20 X
3 pcs	rear tail lamp clip	10.80 X
3 pcs	rear tail lamp clip gormet	8.55 X
1pc	rear tail lamp housing panel	561.00 X
1pc	rear tail door	1,693.50 ✓
1pc	rear tail door inner trim	568.65 X
1pc	rear tail door servo lifter LH	354.11 X
1pc	rear tail door rubber stopper LH	16.20 X
1pc	rear tail door lock	215.40 ?
1pc	rear fender arch protector <i>c/s</i>	196.40 ✓
9pcs	rear fender arch protector clip	28.80 ✓
1pc	rear fender dust cover	186.70 X
8pcs	rear fender dust cover clip	29.60 X
	sub total	12,963.02
	less 20%	2,592.60
	sub total	10,370.42

	BALANCE CARRIED FORWARD		10,370.42	
1 set	reverse sensor	s.nett	250.00	?
1 pc	rear tail door glass inner seal	s.nett	45.00	3012
1 tube	windscreen glass sealant	s.nett	65.00	8012
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		1,000.00	?
	To check wiring system.		60.00	201
	To apply rust proofing on affected areas.		120.00	?
	To apply waterproof sealant on affected areas.		120.00	1
	To apply putty and spray painting on affected areas. (12 surfaces)		950.00	7001
	To install reverse sensors and reverse camera.		120.00	501
	To remove rear glass to enable repair.		150.00	1201
	To remove carpet , trimming and seats to enable repair.		120.00	501
	To transfer tail door accessories.		60.00	✓
	Total		13,430.42	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/11/2022 10:00 (SGT)
Reported by Both
Date of Accident 18/11/2022 13:07 (SGT)
Exact Location of Accident Commonwealth Ave W, Singapore
Additional Location Information
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC4878E

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LOH HWEE PENG PATRICIA (LU HUIPING)
NRIC No SXXXX485J
Email Address iampolarbears@hotmail.com
Mobile Phone No (Phone) +65-90017294
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited
Policy Number / Cover Note Number 5131566512

DRIVER

Name of Driver LOH HWEE PENG PATRICIA (LU HUIPING)
NRIC No SXXXX485J
Date Of Birth 25/10/1978
Occupation Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

