

ASS. REC. BY:

REF:

A/C 22011777/KP

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMJ 2578E

Yr Regn:

02, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Avante c.c.

1591

Colour:

m. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

50700

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMITD 841CMKU 866350

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / (GY) FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/11/22

D.O.I.

25/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

F. m. s.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #11-16,
Singapore 079120

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Estimate bill : TT 41 / 22 / TP / WT

Registration No : SMJ2578E

Make / model : Hyundai Avante

Mileage :

Date : 24 / 11 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SGV478G AND SMJ2578E ALONG
EXIT FROM PUNGOL FIELD TOWARDS SUMANG WALK ON 21 NOVEMBER 2022 AT ABOUT 2014HRS.**

1pc	Rear boot		\$	972.00	✓
1pc	Rear boot emblem		\$	41.00	✓
1pc	Rear boot 'Avante' designation		\$	49.00	✓
2pcs	Rear boot hinge	(Each \$81.00)	\$	162.00	X
1pc	Rear bumper		\$	730.00	✓
2pcs	Rear license lamp	(Each \$54.00)	\$	108.00	?
1pc	Rear bumper lip		\$	486.00	✓
1pc	Rear bumper lip fog lamp (RH)		\$	243.00	X
2pcs	Rear bumper side retainer	(Each \$49.00)	\$	98.00	X
1pc	Rear bumper reinforcement		\$	440.00	?
3pcs	Rear bumper reinforcement bracket (Top)	(Each \$17.00)	\$	51.00	?
2pcs	Rear bumper reinforcement bracket (Bottom)	(Each \$17.00)	\$	34.00	?
	Sub A total :		\$	3,414.00	
	Less 20% discount :		\$	682.80	
	A total :		\$	2,731.20	

Special net items :

1set	Rear bumper parking sensor	\$	200.00	?
1pc	Rear license smart plate & casing	\$	40.00	✓
	B total :	\$	40.00	

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot emblem, rear boot 'Avante' designation, rear boot hinges, rear bumper, rear bumper parking sensors, rear license lamps, rear bumper lip, rear bumper lip fog lamp (RH), rear bumper side retainers, rear bumper reinforcement, rear bumper reinforcement brackets (Top), rear bumper reinforcement brackets (Bottom)..

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

Total amount of Page 1 :

\$ 3,671.20

Tropical Tech Automobile Services*

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #11-16,
Singapore 079120

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Estimate bill : TT 41 / 22 / TP / WT

Registration No : SMJ2578E

Make / model : Hyundai Avante

Mileage :

Date : 24 / 11 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SGV478G AND SMJ2578E ALONG
EXIT FROM PUNGGOL FIELD TOWARDS SUMANG WALK ON 21 NOVEMBER 2022 AT ABOUT 2014HRS.**

Diagnostic and reset rear bumper parktronic sensor fault error by HHT	\$	100.00	50/
To check and refit rear tail lamp wiring harness.	\$	80.00	20/
Under coating on rear damaged portion.	\$	200.00	30/
Putty / primer application, spray painting rear boot, rear boot hinges, rear end panel, rear bumper, rear bumper parking sensors, rear bumper lip.	\$	1,000.00	600/
Balance amount brought from Page 1 :	\$	3,671.20	
Grand final amount :	\$	5,051.20	

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Date of accident: 21/11/22 Time: 8.14pm Location: Sumang Walk
My Vehicle A: SMJ 2578E Vehicle B: SGV 478G Vehicle C: -N/A-

Exit from Punggol Field
towards

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At Approximately 8.14pm, My vehicle SMJ 2578E was driving along Punggol Field road, preparing to turn into Sumang Walk through a filter lane that was directly situated in front of U-stairs Mega Mart.

As I slowed down my vehicle at the filter, coming to a complete stop to look to my right for any possible incoming traffic, the vehicle behind to ~~SGV 478G~~ SGV 478G hit the rear of my vehicle resulting in a boom sound.

I was the driver, my NRIC Number is S8600840H, the passengers behind were my wife and child at the point of impact.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address: gerardlykm@gmail.com

& myself:

Email address: alicia.yltan@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

22/11/22

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/11/2022 15:03 (SGT)
Reported by Both
Date of Accident 21/11/2022 20:14 (SGT)
Exact Location of Accident Singapore
Additional Location Information EXIT FROM PUNGGOL FIELD TOWARDS SUMANG WALK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ2578E

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner GERARD YIP KAI MAN
NRIC No SXXXX840H
Email Address GERARDYKM@GMAIL.COM
Mobile Phone No (Phone) +65-97813291
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Hyundai
Model AD AVANTE 1.6 GLS (A)
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1591

INSURANCE COMPANY

Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number P10518757R01

DRIVER

Name of Driver GERARD YIP KAI MAN
NRIC No SXXXX840H
Date Of Birth 10/01/1986
Occupation Indoor