

Our Job Ref No : 305537427
Date : 30/11/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Irfan

Vehicle Reg No. : SH9489Y

19.11.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **TOKIO MARINE** -- **SKU6003L**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$479.76
 - (b) Labour Charges \$1,241.00
 - Total for Part-By-Part Repair Cost \$1,720.76**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$0.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : _____

Name : Ms. Loke YY

Name : _____

Tel : 62148355

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305537427
REGN NO : SH 9489Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 31.03.2022
DATE/TIME IN : 23.11.2022 11:35
ACCIDENT DATE : 19.11.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0003 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00
0004 04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64

SUB-TOTAL : 479.76

JOB NATURE

0000 L	MERIMEN FEE	11.00	
0001 PB	PANEL BEATING SH 9849Y- TP		700.00
0002 SP	SPRAYPAINT CHARGE		500.00
0003 20-204	REMOVE/REFIX REVERSE SENSOR		30.00

SUB-TOTAL : 1,241.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305537427
REGN NO : SH 9489Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 31.03.2022
DATE/TIME IN : 23.11.2022 11:3
ACCIDENT DATE : 19.11.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,720.76

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO