

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	R	ef:	CS3/ASM22011790/Snp3m4	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	D	ate:	06/12/2022	
	ATTN: LOW GARN	IET	С	ode:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 3087P	Veh. Inspected		SKR 4352H	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04EV3	Excess (\$)		0.00	
	Assign From	LOW GARNET	Assign Date		23/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	RU11015107	Colour		WHITE	
	Odometer	184634 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	MICHELIN		6 mm	
	L/H Front Tyre	225/40 R18	MICHELIN		6 mm	
	R/H Rear Tyre	225/40 R18	MICHELIN		5 mm	
	L/H Rear Tyre	225/40 R18	MICHELIN		5 mm	
4.	Description of Damages					
	THE VEHICLE SU	EHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.				
5.	General Information					
	Accident Date	13/11/2022	Inspect Date / Tir	ne	23/11/2022 (12:00 PM)	
	Survey held at	GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000-\$10,000					
5b. Estimate Days of Repair						
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days				

Report Ref No. CS3/ASM22011790/Snp3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser