

Service Request Details

Claim	S2M04FE3
Reference	CS3/ASM22011792/Gwp3m4 
Loss Date	19 November 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	23 Nov 2022 3:51:49 PM
Request Date	23 November 2022
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information	
Incident	SLR7273X
Vehicle	
Registration #	
Make	TPVD Kia
Model	Carens
Service Address	
, , ,	
Primary Contact/Insured	

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2301057.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2023
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2023
 SLR 7273X Preliminary Advice.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 February 2023
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	23 November 2022
 SLR7273X TP GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	23 November 2022