

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS : COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575777

65508755

LKK Auto Consultants hence notify

To resurvey before/after spray painting

To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

JOB NO

REGN NO

MILEAGE

MAKE

MODEL

DATE OF REGN

DATE/TIME IN

ACCIDENT DATE

: 305537313

: SH 9601P

: 0000000000

: HYUNDAI

: I-40

: 13.12.2017

: 21.11.2022 14:10

: 20.11.2022

JOB / PARTS DESCRIPTION

Acknowledged by Repairer

Signature:

Date:

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	— Re
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	X nn
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	— ntc
0004	04-01-0103-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00	— ntc
0005	04-01-0103-0852-G	REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	— Sep
0006	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	X
0007	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	X } nn
SUB-TOTAL : 1,156.32							

JOB NATURE

0000	PB	PANEL BEATING	400.00	280
0001	SP	SPRAYPAINT CHARGE	300.00	250
0002	17-01	CHECK ALL LIGHTING	50.00	X nn
0003	L	REMOVE/REFIX REVERSE SENSOR	50.00	40
Advertisement logo - bumper \$50				
" " - Render \$200				
2 Days.				
4/5				
Gm Qup				
21/11				
Gpm				