



Your Ref: 22.30262

Date: 16th Dec 2022

Our Ref: CS3/ASM22005112/Evp3m4-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMT 3940H

INSURED VEHICLE: SH 7642J

ACCIDENT DATE: 25/05/2022

We thank you for your instruction on 24/11/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMT 3940H from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles SMT 3940H and SH 7642J.
- c) Final Repair Bill of SMT 3940H from M/s LYS Engineering.
- d) Colour damaged vehicle photographs of SMT 3940H.

Pre-Repair Inspection Date: 27/06/2022 at M/s LYS Engineering, 7 Soon Lee Street #01-39, Singapore 627608.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMT 3940H
Make & Model	: Honda Vezel 1.5X Cvt Abs D/Airbag 2WD 5DR
Year of Registration	: 2020
Chassis Number	: RU11319946
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.