		ASSIGNMI	INT	
From:	Date:	Veh No:	GB69986k	C Yr Regn: 2017, Dec.
Estimated Cost:				Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD R	ES / EVA / INV / MV	Т	ruck / Trailer or	
To Inspect Vehicle No:		Make:	Toyota Hiac	e c.c 2582
at Workshop m/s		Colour	Black.	A/C: Insured / Std / NI / NA
of		Sp.Read	ding 149/28	T/Radio: Insured / Std / NI / NA
nsured:		Eng/No:		
Policy No.		C/No:	KPH 2010	0236067*.
Claims No.		Gen. Co	ond: Good/ Fair / Poor / Bur	rnt
Sum Insured:	Excess:	Steering	Inorder/ Jammed / Leake	ed / Burnt or
(Client's Record)		Brake:	Inorden / Jammed / Leake	ed / Burnt or
Make of Veh:		Modí :	Nil / S/Rim / STD A/Rim	
	_	Tyre Siz		0215
(Policy Condition)	_		R: /85/	80 RIS.
Remark: The veh had comme	3			A / MIC / OHTSU / PIR / SUMI /
repair at the time of	inspection.	TOYO	YOKO or	
Bal. or Market Value:		Front		Rear
DAC Accident Rport:	Consistent? : Yes or I	No R/Bal.	06 mm	R/Bal. 06 mm
GIA / PR Seen:	Consistent? : Yes or I	No L/Bal.	06 mm	L/Balmm
Est. Repairs:	days Res.: Yes or	No D.O.A.		D.O.I. 2/11/22
Lum Sum:	% 3 Val.: Yes or	No Survey	held at SA	1
CA / REV / REP. / 24	HRS	Des. of	Damages : Frt / Rear / O/	'S N/S U/C Rooftop or
Date: Person	Vel Contacted:	hicle: IN / OUT		
		The	U/C / Chassis frame / Bo	ody Structure affected due to collision.
Date / Time Action / Instr	ana,		•	
	CANTO (· · · · · · · · · · · · · · · · · · ·	,	
		*	•	
mv:				
PV:				
Nett:				
				5 MI
Pate/Time, File Pass to?	: Preli. Report	Davis C	f Damain	
	: Final Report		f Repair:ey No. of Trip:	Sun ou Face
Pate/Time, File Return to?	. , mai Kabolf	Kesurv	=y 140. Of 111p:	Survey Fee: Transportation:
		Add Fee:	Site Insp (\$) 8 ÷ RS, SI
AND THE RESIDENCE OF THE PARTY				
)			Interview (\$) Photos

SM-China Taiping
- Lkk.

SS2X22BL0008 / SME MOTOR PTE LTD ENTRY DATE & TIME: 21/11/2022 13:06 (SGT) SUBMITTED BY: Chia Pei Ying VERSION: 1 (21/11/2022 13:06 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

21/11/2022 13:06 (SGT)

Owner

20/11/2022 12:40 (SGT)

CTE, Singapore

TWDS AYE BEFORE BRADDELL

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBG9986K

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

Yes

JIE NI CHE JOS

53386788J

JOSHUA.HUANGG@GMAIL.COM

(Phone) +65-85988888

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Toyota

Hiace

Employment

No - Claiming third party

Commercial vehicle

Auto 2982

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

EQ Insurance Company Ltd DMCPHQ21-004184

DRIVER

Name of Driver

NRIC No

Date Of Birth Occupation

JOSHUA HUANG S8913220G

18/04/1989 Outdoor

Accident report SS2X22BL0008

Page 1 of 13

Date Of Driving Pass 19/08/2016 Driving experience 6 YEARS AND 3 MONTHS Gender Female Mobile Number (Phone) +65-85988888 Alt. Phone Number **Email Address** JOSHUA.HUANGG@GMAIL.COM Address BLK 139 SIMEI STREET 1 #02-02 Address complement Postcode 520139 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

PASSENGER 1

Name TAN KAI YUN Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG CTE TOWARDS AYE ON THE THIRD LANE FROM THE LEFT. AS I WAS TRAVELLING STRAIGHT BEFORE BRADDELL EXIT, VEHICLE IN FRONT BRAKE AND STOP. I ALSO APPLIED MY BRAKE TO STOP WHEN SUDDENLY, ONE M/CAR (SLL2511Z) CAME FROM MY REAR AND COLLIDED ONTO THE REAR PORTION OF MY STATIONARY STOP VEHICLE. AFTER THE ACCIDENT, I CAME OUT OF MY VEHICLE AND REALISED A TOTAL OF 3 VEHICLES INVOLVED.

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLL2511Z

Chain Collision

Clear

Dry



Vehicle Manufacturer	_
Vehicle Model	_
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	S=
Contact Number	
Address	-
Address complement	-
Postcode	_
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR119F
Vehicle Manufacturer	-
Vehicle Model	_
Vehicle Variant	_
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	-
Contact Number	
Address	_
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	JOSHUA HUANG
Gender	Male
Phone No	_
Address	-
Address Complement	
Post Code	
Approximate Age Years Old Injuries Sustained	-
Injured person in which vehicle?	GBG9986K
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No
INJURED 2	
Name of injured person	TAN KAI YUN
Gender	Female
Phone No	-
Address	
Address Complement	
Post Code	-
Approximate Age Years Old	-
Initiation Constalined	5.
	-
Injured person in which vehicle?	GBG9986K
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formittust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

NI UEN 533867883

Policyholder's Signature / Date &

BRADDELL

BEF

Aye

Pospecial

Sketch Plan

Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

A: GBG 9986K

Describe Circumstances of the Accident

The state of the s
I WAS TRAVELLING ALONG CTE TOWARDS AYE ON THE THIRD
LANG FROM THE LEFT, AS I was TRAVELLING STRAIGHT BEFORE
BRADELL EXIT, VEHICLE IN FRONT BRAKE AND STOP, I ALSO APPLIED
My BRAKE TO STOP WHEN SUDDENLY ONE MICAR SLL 25117 CAME
FROM MY REAR AND COLLIDED ONTO THE REAR PORTION OF MY
STATIONARY STOP VEHICLE. AFTER THE ACCIDENT I CAME OUT OF MY VEHICLE AND REALISED A TOTAL OF 3 VEHICLES INVOLVED.
MY VEMICLE AND REALISED A TOTAL OF 3 VEHICLES INVOLVED.
· ·

Declaration

UEN 53386788J

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel