ARC Automotive Repair Centre Pte Ltd CO. Reg. No.: 201312913C GST Reg. No.: 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

TO Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

ESTIMATE NO.: EST2211-636 -TG

DATE: 24-Nov-2022

VEHICLE REG. NO.: SMD4851J

VEHICLE MAKE: HYUNDAI ELANTRA AD 1.6 GLS AT

FOR SURVEYOR

ECTIMATE DEDAID CO

NO.	DESCRIPTION	QUANTITY	UANTITY UNIT COST			TOTAL COST	
	SPARE PARTS	C.A.M.	0.000	Omir Cost		10142 0031	
1	Front Bumper Col/	1	\$	680.00	\$	680.0	
2	Front Bumper Retainer RH ⊀	1	5	60.00	-	60.0	
3	Front Bumper Retainer LH 🗡	1	\$	60.00	-	60.0	
4	Front Bumper Top Rubber Seal Mc	1	\$	100.00	\$	100.0	
5	Front Reinforcement 7.	1	\$	780.00	\$	780.0	
6	Front Sponge	1	\$	240.00	\$	240.	
7	Front License Garnish de/	1	\$	60.00	5	60.	
8	Front Grille Assy	1	\$	780.00	\$	780.	
9	Front Grille Moulding Cra /	1	\$	250.00	\$	250.	
10	Front Emblem 🔥 /	1	\$		\$	100.0	
11	Headlamp RH 7.	1	\$	1,280.00			
12	Headlamp LH 7	Mana 111 7		1,280.00	\$	1,280.	
13	Headlamp Bracket RH 7	1	\$	80.00	\$	1,280.0	
14	Headlamp Bracket LH 1	1	\$	80.00	\$	80.0	
15	Support Panel Top Cover CA	1	\$	240.00		80.0	
16	Support Panel 7	1	\$	800.00	\$	240.	
17	Bonnet run	1	\$		\$	800.	
18	Bonnet Lock X	$+\frac{1}{1}$	\$	1,500.00	\$	1,500.	
19	Rear Bumper de/	1	\$	150.00	\$	150.	
20	Rear Bumper Retainer RH	1	\$	680.00	\$	680.0	
21	Rear Bumper Retainer LH	1	\$	60.00	\$	60.0	
22	Rear Bumper Lower	1		60.00	\$	60.0	
23	Rear Bumper Reflector RH ?	1	\$	380.00	\$	380.0	
24	Rear Bumper Reflector LH 🗶	1	\$	80.00	\$	80.0	
25	Rear Reinforcement ?	1	\$	80.00	\$	80.0	
26	Rear Bumper Mounting Bracket RH - 86634F2000 7	1	\$	350.00	\$	350.0	
27	Rear Bumper Mounting Bracket LH - 86633F2000 7	1	\$	25.00	\$	25.0	
28	Rear Smart Key Antenna Assy - 95420F2200 ?	1	\$	25.00	\$	25.0	
9	Rear Bumper Undercover - 86690F2000		\$	90.00	\$	90.0	
30	Rear Bumper Wiring Harness - 91890F2010	1	\$	90.00	\$	90.0	
1	Bootlid reger		\$	150.00	\$	150.0	
32	Bootlid Hinge RH	1	\$	2,000.00	Ş	2,000.0	
13	Bootlid Hinge LH 🔸		\$	100.00	\$	100.0	
4	Bootlid Lock X		\$	100.00	\$	100.00	
5	Bootlid Striker 🗶		\$	150.00	\$	150.00	
16	Bootlid Rubber Seal 🗡	1	\$	30.00	\$	30.00	
17	Bootlid Inner Trim - 81750F2000TRY		\$		\$	140.00	
8	Bootlid Lamp RH X		\$		\$	180.00	
9	Bootlid Lamp LH		\$		\$	350.00	
		1	\$	350.00	\$	350.00	

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586 Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

ESTIMATE NO. :

EST2211-636 -TG

DATE: 24-Nov-2022

VEHICLE REG. NO.: SMD4851J

VEHICLE MAKE: HYUNDAI ELANTRA AD 1.6 GLS AT

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST		1	TOTAL COST
40 E	Bootlid Lamp Special Clips 🗡	4	\$	6.00	\$	24.00
41 E	Bootlid Emblem "Elantra" 🖊 /	1	\$	65.00	\$	65.00
42 E	Bootlid Emblem 🎍 /	1	\$	80.00	\$	80.00
43 E	Bootlid Emblem "S"	1	\$	50.00	\$	50.00
44 E	End Panel Top Garnish 🗡	1	\$	120.00	\$	120.00
45 E	End Panel Assy rumV	1	\$	500.00	\$	500.00
46 S	Spare Tyre Board - 85710F2100MC		\$	265.00		
47 R	Rear Floor Panel 🗡	1	\$	750.00	\$	750.00
		Т	otal	Spare Parts	\$	15,844.00
	PECIAL NETT					
	Front Number Plate with Casing 54/	1	\$	40.00	\$	40.00
	Rear Number Plate with Casing 🗡		\$	40.00	\$	40.00
50 F	Front Bumper Clip ~~/		\$	4.00	\$	40.00
51 B	Bonnet Insulator Clip 💢 🖍 🧥		\$	4.00	\$	40.00
52 R	Rear Bumper Clip ~/		\$	4.00	\$	40.00
	Coolant 🗡 🔨	1	\$	35.00	\$	35.00
54 R	Reverse Sensor Sur/	1	\$	280.00	\$	280.00
55 S	ealant For Repair Areas (End Panel, Bootlid)	2	\$	60.00	\$	120.00
		То	tal S	pecial Nett	- 22	635.00
<u> </u>	ABOUR				100	GH P
-	emove and Refit Front & Rear Affected Area	1	\$	2,000.00	\$	2,000.00
57 Sp	oray Painting - Whole Front & Whole Rear, End Panel	1	\$	2,000.00	\$	2,000.00
	lagnostics and Rectify Fault Codes	1	\$	150.00	\$	150-00
	ransfer Bootlid Fitting & Mechanism to New Bootlid	1	\$	80.00	\$	80.00
	emove and Replace Rear Reverse Sensor	1	\$	80.00	\$	80.00
	pply Anti-Rust Costing for Repaired and Replace Panels	1	\$	80.00	\$	80.00
	emove and Refit A/C Condenser, Radiator Including A/C Gas	1	\$	100.00	\$	100.00
63 Ch	neck and Rectify Electrical Wiring	1	\$	30.00	\$	30.00
timate pr	epared by: KenGuan			Total Labour	5	4,520.00
Juliuonal pa	s an estimate based on our inspection and does not cover any arts/labour which may be required after work has been started.	Am		Before Excess		20,999.00
orn or dan	naged parts are discovered which may not be evident on first Because of this, the above price are not guaranteed.			Add GST @ 7%		1,469.93

Page 2 of 2

inspection. Because of this, the above price are not guaranteed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged pari(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RARIL
Hp 90010068
8 days
28/11/22 0/610
Rosy Ar repar

Total Amount Payable \$

22,468.93

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

A. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/11/2022 13:23 (SGT) Reported by Both **Date of Accident** 22/11/2022 08:40 (SGT) Exact Location of Accident PIE, Singapore Additional Location Information PIE TOWARDS CHANGI AIRPORT BEFORE JURONG EAST FLYOVER SINGAPORE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD4851J

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner ARNOLD STANLEY NRIC No S9050262Z **Email Address** mail.arnoldstanley@gmail.com Mobile Phone No (Phone) +65-91291559 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Hyundai Model Elantra Variant HYUNDAI / ELANTRA AD 1.6 GLS AT (AMS) Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle?

No - Claiming third party Vehicle Category Private car Transmission Auto CC 1591

INSURANCE COMPANY

Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited. Policy Number / Cover Note Number P10608701R01

DRIVER

Name of Driver ARNOLD STANLEY NRIC No S9050262Z Date Of Birth 11/12/1990

ST

Indoor Occupation 11/02/2010 Date Of Driving Pass 12 YEARS AND 9 MONTHS Driving experience Male Gender (Phone) +65-91291559 Mobile Number Alta Pagne Number mail.arnoldstanley@gmail.com Email Address 815C CHOA CHU KANG AVENUE 7 #18-45 Address Address complement Postcode 683815 Is the driver the policyholder? Yes If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name POH XIU JING, RUTH Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED STATEMENT RECORDED BY ANNIE - PROGRESSIVE CAR CARE PTE LTD TEL 67415336 ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Yes Yes DETAILS OF OTHER VEHICLE PROPERTY 1

Accident report SP1822BM0006

Vehicle Registration Number

SLS4518E

14	
Vehicle Manufacturer	
The state of the s	
Vehicle Variant	.=
Vehicle Colour	
Vehicle Category	-
Name of Date	Private car
Contact Number	ZEN
Address	(Phone) +65-93670030
Address complement	•
Postcode	-
Insurance Company Name	-
Nature Of Damage	•
Nature Of Damage Details of property damaged in accident	
No. Of Passanger (Including Driver)	•
rio. Of rassenger (including briver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMN5457E
Vehicle Manufacturer	•
Vehicle Model	1700 1700
Vehicle Variant	
Vehicle Colour	-
Vehicle Category	-
	Private car
Name of Driver	5.70
Contact Number	(Phone) +65-90499868
Address	-
Address complement	
Postcode	3
Insurance Company Name	-
Nature Of Damage	-
	(5)
Details of property damaged in accident	
No. Of Passenger (Including Driver)	•

INJURED PERSONS DETAILS

INJURED 1	-
Name of injured person	ARNOLD STANLEY
Gender	Male
Phone No	(Phone) +65-91291559
Address	815C CHOA CHU KANG AVENUE 7 #18-45
Address Complement	
Post Code	683815
Approximate Age Years Old	•
Injuries Sustained	•
Injured person in which vehicle?	SMD4851J
Were seat belts worn?	•
Was this injured conveyed to hospital by ambulance?	
INJURED 2	
Name of injured person	POH XIU JING, RUTH
Gender	Female
Phone No	-
Address	
Address Complement	
Post Code	
Approximate Age Years Old	
Injuries Sustained	##-
Injured person in which vehicle?	- CMD40541
Were seat belts worn?	SMD4851J
A STATE OF THE PARTY OF THE PAR	-

Was this injured conveyed to hospital by ambulance?

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be as <u>invitiful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
 report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposps.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



1

	around	8.40	an ,	travelling	00.	the	PIL	الان رعام
Chino	jer J	- sav t	that t	ne cor	in fro	nt t	nad	Slowed
dow	and	pie pared	to stop	, I d	id the	Same		
As	L 2002	doing	so, I	felt co	· impo	act	at	my
(eac	cans	my my	car	to Sura	ic forw	md o	nol	collide
w	n the	front	car (desprie	my eff	lats	to	break
Fo	om car:	SWM:	54C4 C					52
		SMD 45						
	Rear car.	SLS 4		-				
8					SLS 45			
		-7				1 5	but	L
	ere were	5 oth	er cors	behind	St. 5-4-8 5	1 -	-	
Th				behind behind				net
Th	s inform		the cor	behind		18 E	had	

Declaration

I/We declare the foregoing particulars are true in every respect.

1:15 pm

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurence. Kindly check with your insurer for more details.

Policyhoder's Signatura / Cate & Time

Oriver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

2

S. REC. BY	SSIGNMENT
\	
om: Date:	Vehille: SMO 4851) Yr Regn: 2018 1Au4
limated Cost	Type: Micari M. Cycle / Bus / Van / Lony / Tadi/ Prime Mover/
TP WS TP RES OD RES EVA INV. INV	Trucki Trailer or
Inspect Vehicle No: SMD 48517.	Make: Hymnori Euntrali64LSAT Ex 1591
Workshop 19/5 Award WE REPAIR CTR	Golour RGO AC: Insured/Std/NINA
Toth Guan	Sp.Reading 76155 TilRadic: Insured Std (1917) NA
sured: AS	Eng/No.
olicy No.	C/No: FMHD841CMJU726012
Jaims No.	Gen. Cond: Good (Fair) Poor / Burnt.
um Insured: Excess:	Steering: morder: Jammed / Leaked / Burnt or
(Client's Record)	Brake: Morder/ Jammed/Leaked/Burnt or
ake of Veh:	Medi: NH JERRim J STD AFRIM or
-,	Tyre Size: F: 195/65R15
(Policy Condition)	R: W
emark: The veh had commenced its N/S	OIS BS:/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PR/SUM/
repair at the time of inspection.	TOYOTAOKO or
al, or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal mm R/Bal (mm
IA / PR Seen: Consistent?: Yes or No	17Bal. 6 mm LBal. 6 mm
st Repairs: days Res.: Yes or No	D.O.A. 22/11/22 B.O.I. 25/11/22
m Sum: % 3 Val.: Yes or No	Survey held at ARC
A / REV / REP. / 24 HRS	Des. of Damages First Rear Ols / N/S / U/C / Rooftop or
Vehicle: 1N	1-OUT
ate: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time : Action / Instruction	
repair limit—45K	
	<u> </u>
ste/Time, File Pass to?	Days Of Repair:
ate/Time, File Pass to? : Prefit. Report : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee;
ate/Time, File Pass to? Prefi. Report Final Report ate/Time, File Return to?	Days Of Repair:

:Weekend (\$

Report Format: Lump Sum fl.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Owner ID:	Singapore NRIC 262Z
Vehicle No.: Vehicle to be Exported: Intended Deregistration Date: Vehicle Make: Vehicle Model: Primary Colour: Manufacturing Year: Engine No.: Chassis No.: Maximum Power Output: Open Market Value: Original Registration Date: First Registration Date: Transfer Count: Actual ARF Paid:	SMD4851J No 28 Nov 2022 HYUNDAI ELANTRA AD 1.6 GLS AT (AMS) Red 2018 G4FGJU232915 KMIHD841CMJU726012 93.8 kW (125 bhp) \$12,477.00 23 Aug 2018 0 \$12,477.00
PARF Eligibility: PARF Eligibility Expiry Date: PARF Rebate Amount: COE Expiry Date: COE Category: COE Period(Years): QP Paid: COE Rebate Amount: Total Rebate Amount: The information contained herein is correct as at 28 Nov 2022	Yes 22 Aug 2028 \$9.357.00 22 Aug 2028 A - Car up to 1600cc & 97kW (130bhp) 10 \$33.798.00 \$19.379.00 \$28,736.00

Hyundai Elantra 1.6A GLS

Overview

Financial

Accessories

Similar

Research

Photos

Мар



ESTABLISHED SINCE 1989





Price	\$74,800		
Depreciation	\$12,050 /yr View models with similar depre	Reg Date	30-Aug-2018 (5yrs 9mths 1day COE left)
Mileage	70,648 km (16.6k/yr)	Manufactured	2018
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$26,609 as of today (change)	OMV	\$10,922
COE	\$31,997	ARF	\$10,922
Engine Cap	1,591 cc	Power	93.8 kW (125 bhp)
Curb Weight	1,345 kg	No. of Owners	1