

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHB66295

DATE 17.11.2022

MAKE REG 23.01.2020

MODEL : HYUNDAI IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR WING MIRROR LH / <i>OA</i>			\$1,391.70
	<b>SUB TOTAL</b>			<b>\$1,391.70</b>
	<b>LESS 20%</b>			<b>\$278.34</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,113.36</b>
1	FRONT DOOR COMFORT STICKER / <i>MC</i>			\$75.00
	<b>Labour Charge</b>			<b>\$75.00</b>
	Panel Beating			\$150.00
	Spray Painting Charge			\$120.00
	<b>TOTAL LABOUR</b>			<b>\$270.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$1,458.36</b>
<i>1 Days</i> <i>4/5</i> <i>Good Q of</i> <i>21/11</i> <i>4pm</i>				
<div> <div>LKK Auto Consultants hence notify the Repairer of the following:</div> <div> <div>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.</div> <div> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div> </div> <div> <div>Acknowledged by Repairer</div> <div>Signature:</div> <div>Date:</div> </div> </div>				

100  
100