

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING)	APORE) PTE LTD	Ref	CS/ASM22011882/Gvp3e2	
	10 MARINA BOUL #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Dat	e: 08/03/2023	
	ATTN: HO WINNIE		Cod	le: HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3704Y	Veh. Inspected	SNG 2979K	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M04FH8	Excess (\$)	0.00	
	Assign From	HO WINNIE	Assign Date	25/11/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AE IONIQ HEV 1.6 DCT	c.c	1580	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	KMHC851CVNU290269	Colour	SILVER	
	Odometer	18318 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/11/2022	Inspection Date	25/11/2022	
	Survey held at	AUTO INSURE PTE LTD			
	6 MARSILING LANE S739145				
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				