

S. REC BY: T. L. J. A. A.

REF: CS3 / E. Q. / 22.01.89 / T. J. Y. 3

ASSIGNMENT

from: _____ Date: _____
 estimated cost: _____
 ID / TP / WS / TP RES / OD RES / EVA / INV / MV
 to inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 970K.
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SMJ 2145X Yr Regn: 2019, Feb
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Vios C.C. 1496
 Colour: Blue A/C: Insured / Std / Nil / NA
 Sp. Reading: 162273 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: MR12B 23F 3301 66537
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirella
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 8 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.L. 28/11/2012 12pm
 Survey held at Wan Yu
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Range: \$8000-9000, 9 days.</u>

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
S + RS. Sl.	
Photos	

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)

Report Format: _____