

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details				
Registration Number	SG5597A			
Case Reference Number	BUS/11/22/5022			
Registration Date	2/9/2017			
Company Type	SMRT Buses Ltd			
Make	VOLVO B9TL DD			
Model	VOLVO			
Name of Driver	Ji Yanchao			
Type of Accident	Side Swipe			
Accident Date and Time	11/16/2022 7:04 PM			
Accident Reported Date and Time	11/23/2022 11:04 AM			
Is Surveyor Required?	No			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number				
Special Instruction to ARC,if any	Bus Right front body sustained scratches. TP vehicle (SLF4989C): Left rear sustained scratches. (CHINA TAIPING INSURANCE)			
Prepared Date and Time	11/28/2022 10:17 AM			
Chassis Number	YV3S4P928HA180913			
Mileage				
Work Shop				
Repair Completion Date and Time				

Section B - Summary of Repair Estimates							
Summary of Repair Estimates							
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$795.00	\$0.00					
Total Spray Cost	\$616.00	\$0.00					
Total Spare Part Cost	\$0.00	\$0.00					
Total Other Cost	\$0.00	\$0.00					
TOTAL COST	\$1,411.00	\$0.00					
Lump Sum Total	\$0.00	\$0.00					
Number of Repair Days	3.0						
Prepared / Adjusted By	Jeong Choon Hwee						
ARC / Surveyor Sign Off Date	28/11/2022 10:18 AM						
Signature	×	×					
Remarks							

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 28/11/2022
User ID : JeongCH



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 28/11/2022
User ID : JeongCH

	Section D - Detail	s of Repair E	stimates				
Part 1 - Labour Works							
Job Scope	Quotation fro	Quotation from AR			Adjusted by Surveyor, if applicable		
TO REPAIR RH PORTION		\$795.00					
Total Labour		\$795.00					
Part 2 - Spray Painting & Panel Beating Related Work							
Job Scope	Quotation from A		n ARC			Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$616.00					
Total Spray Painting & Panel Beating		\$616.00					
Part 3 - Other Costs - Accident and Accident Repair R	elated Expense						
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable		
Total Other Costs							
Part 4 - Spare Parts / Material Usage							
Part Number Portion Stock Number Part Nam	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
Total							
Added Spare Parts / Material Usage After Surveyor Si	ned off						
Part Number Portion Stock Number Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total							