

(08/11/13) WE

ASS. REC. BY: AKC

REF:

CS3/ABM22011929/RUP3

913H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 7009Gat Workshop m/s JCM RENTALof BURNT BROWN CRESCENT #04-40 WGBHAInsured: SHC 2495G ASM

Policy No. _____

Claims No. S2M04F69


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 52K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 7009G Yr Regn: 20/6 / 86PType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 340R SEAN / SL cc 1496Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading 186328

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3M6BM42A860344931

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD / Rim or

Tyre Size: F: 205/60R16R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYOTA / FOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/11/22D.O.I. 28/11/22Survey held at JCM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR & REAR

The U/C / Chassis/frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 24K

5/12/22

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - TK & R / 11-12 days

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 5/12/22-typist

Report Format :

Days Of Repair: 12

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) \$ + RS. \$ _____

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	913H
Vehicle No:	SLF7009G
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	White
Manufacturing Year:	2016
Engine No:	P520371589
Chassis No:	JM6BM42A8G0344931
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,070.00
Original Registration Date:	06 Sep 2016
First Registration Date:	06 Sep 2016
Transfer Count:	2
Actual ARF Paid:	\$12,070.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Sep 2026
PARF Rebate Amount:	\$7,845.00

COE Expiry Date:	05 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$20,103.00
Total Rebate Amount:	\$27,948.00

The information contained herein is correct as at 29 Nov 2022

OK

Mazda 3 1.5A Sunroof

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

通利

Thong Lee Trading Pte Ltd

Established since 1969

New & Used Cars | Consignment Car | Hire Purchase | Motor Insurance

Price	\$52,800		
Depreciation ⓘ	\$12,240 /yr View models with similar depre	Reg Date	29-Sep-2016 (3yrs 9mths 30days COE left)
Mileage	N.A.	Manufactured ⓘ	2016
Road Tax ⓘ	\$682 /yr	Transmission	Auto
Dereg Value ⓘ	\$27,747 as of today (change)	OMV ⓘ	\$16,738
COE ⓘ	\$58,201	ARF ⓘ	\$11,738
Engine Cap	1,496 cc	Power	88.0 kW (118 bhp)
Curb Weight ⓘ	1,321 kg	No. of Owners ⓘ	3