

 Service Request Details

Claim	S2M04F69
Reference	CS3/ASM22011929/Rvp3m4 
Loss Date	18 November 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	21 Nov 2022 11:45:51 AM
Request Date	28 November 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SLF7009G
Vehicle	
Registration #	
Make	TPVD
Model	Mazda

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2207539.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 LKKPhotos.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 SLF 7009G IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 December 2022
 SLF7009G - TP GIA REPORT - 2ND VEH.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	28 November 2022
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	28 November 2022
 SDH9928A - TP GIA REPORT - 1ST VEH.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	28 November 2022
 SHC2495G - OI VIDEO.mp4	Evidence	Videos	HO Winnie	28 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	28 November 2022
 SHC2495G - OI GIA REPORT - LAST VEH.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	21 November 2022