

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatzleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 02-Nov-22

Estimate no.

1192

Plate No. FBB1616H

Model. SPARK 135

Surveyor's columns

| S/N | DESCRIPTION (s) | PRICE (\$) | REMARK | PRICE (\$) |
|-----|---------------------------|---------------------------|---|------------|
| 1 | FORK SET | \$ 350.00 | sh sw 120 | |
| 2 | FORK T-UNDER BRACKET | \$ 280.00 | run | |
| 3 | STEERING CONE | \$ 120.00 | run | |
| 4 | FRONT SPORT RIM | \$ scr 200.00 | x sw \$50 | |
| 5 | FRONT TYRES SHAFT | \$ 100.00 | run | |
| 6 | ECU & CDI | \$ 350.00 | x run | |
| 7 | FRONT NUMBER PLATE | \$ SN 15 30.00 | bf | |
| 8 | FRONT DAY LIGHT SET | \$ 250.00 | run 180 | |
| 9 | HANDLE BAR | \$ 300.00 | run | |
| 10 | MIRROR SET | \$ 150.00 | dis 80 | |
| 11 | CLUTCH LEVER | \$ 80.00 | at 40 | |
| 12 | INNER COVER | \$ 280.00 | run 180 | |
| 13 | INNER PANEL | \$ 150.00 | x run | |
| 14 | COVERSET | \$ 450.00 | run 280 | |
| 15 | FRONT FOOTREST BAR | \$ 250.00 | x run | |
| 16 | FRONT FOOTREST RUBBER | \$ 50.00 | at | |
| 17 | HANDLE BAR BRACKET | \$ 280.00 | x run | |
| 18 | FRONT FAIRING INNER COVER | \$ 80.00 | run | |
| 19 | Front fender | \$ 60.00 | cut | |
| 20 | BODY ALIGNMENT | \$ 300.00 | 7.20 x run | |
| 21 | HEAD LIGHT | \$ 250.00 | run | |
| 22 | HORN STAY | \$ 280.00 | x run | |
| 23 | LABOUR | \$ 500.00 | 300 | |

950
 10/- 855
 SN 185
 300
 1435
 1/58 1100, 3 days

Tanf... 47495749
 w/ 28/11/22 @ 340 p
 4/5 Resurvey after repair
 To check repair limit.
 Tanf... & ...
 3-4 days

Less 10% \$ 518.00
 \$ 5,180.00
 Sub Total : \$ 4,662.00
 GST 7% \$ 326.34
 Total: \$ 4,988.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*
 This is computer generated no signature is required.