

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INDIA INTERNATION	ONAL INSURANCE PL		Ref:	CS/MCS22011938/Avy3e2	
	C/O MCLARENS S		Date:	02/02/2023		
	61 ROBINSON RO #09-01, 61 ROBINS	SON, SINGAPORE 068893				
				Code:	III2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	DRIVING BOC	Veh. Inspected		SMK 4078M	
	Policy No.	C22-10/35/PL-III	Coverage (\$)		0.00	
	Claim No.	LPL2022D0010534	Excess (\$)		0.00	
	Assign From	ERNEST KHONG	Assign Date		28/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA JAZZ	c.c		1318	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JHMGK3850KS212980	Colour		BROWN	
	Odometer	60885 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	175/65 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	175/65 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	175/65 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	175/65 R15	YOKOHAMA		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/11/2022	Inspection Date	е	29/11/2022	
	Survey held at	SM AUTOMOTIVE				
	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					
	I .					