

ASS. RECIB: Merimen REF: as/ TM/ 2201/ 946/ Tug3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/s _____

of _____

Insured: **SMU 2845B**

Policy No. **MP005301**

Claims No. **M2206743**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Merimen



Veh No: SMU 39093

Yr Regn: 2022 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BYD New E6

c.c. 70KW

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 3971

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LC 0CE 47C8 N00115LY

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: With / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Chao Yang

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 26/11/2022

Survey held at Comfort Lodge

Des. of Damages Rear 6/s

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 29/11/22

Date / Time Action / Instruction

2/12/22 Final fig \$2792.98 confirmed by email (Red 187.62, 6%)

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) 2/12/22-typist

Rep. Format: Merimen

Lum Sum / L.B. / P. \$2792.98

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: _____

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/11/2022
Vehicle Reg. No.:	SHA3909J	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	BYD ALL-NEW E6, 2.0 (A)	Vehicle Reg. Date:	31/05/2022
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	1814TZXS321037339	Chassis No:	LC0CE4DC8N0011514
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,119.60
Miscellaneous Items	11.00
Labour	850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,980.60
+ GST 7.00% (S\$)	208.64
Nett Amount (S\$)	3,189.24

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2022)**Parts:** 143 BYD ALL-NEW E6 2.0 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA3909J/28/11/2022 16:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	de ✓ *2,013.75 FL
2	1		*REAR BUMPER MOULDING	528.72 20.00	0.00	de ✓ *528.75 FL
3	10		*REAR BUMPER CLIPS	20.00	0.00	de ✓ *22.00 FL x nn
4	1		*REAR BUMPER MAT	0.00	0.00	de ✓ *50.00 F
5	1		*REAR BUMPER LINE STICKER	0.00	0.00	de ✓ *18.00 F
				Sub Total (S\$)		2,632.50
				- List Item Discount on L Items (S\$)		512.90
				Total Parts (S\$)		2,119.60

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA3909J/28/11/2022 16:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400. 500.00
2	SPRAYPAINT	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
Gross Labour Cost (S\$)			850.00

ComfortDelGro Engineering Pte Ltd/SHA3909J/28/11/2022 16:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfilm 97495747
wp' 29/11/22 @ 10am -
p/p heavy before paint
2 days
tanfilm e/kh auto-con

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 24 Senoko Loop Singapore 75815
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 72
45 Pandan Road Singapore 609286 501 Yehun Industrial Park A Singapore
326 Ubi Road 3 Singapore 408649

Date/Time: 28.11.2022 15:55

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 5328064

JC NO: 305538070

CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL. (R) 65508755 (O)

DISCOUNT CARD NO.


REGN NO: SHA3909J	MILEAGE
MAKE: BYD	FUEL E.....1/2.....
MODEL NEW E6	DATE/TIME IN 26.11.2022 20:30
YR OF MANU. 31.05.2022	TARGET DATE
CHASSIS CODE LCOCE4DC8N0011514	COMPLETION DATE/T

JOB DESCRIPTION

Accident Date: 26.11.2022
NATURE: 3P.26.11.22

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:
I/C No.:
Vehicle No.: SHA3909J J TOKIO

Vehicle No.: SHA3909J

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard