


ASS. RECIBY: Tan Jun

REF: as/ TM/ 2201/ 946/ Tug3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / NS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: Suman  
Vehicle: IN / OUT

Veh No: SMA 39093 Yr Regn: 2022 May  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: BYD New E6 c.c. 70KW  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: 3971 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: LC0CE47C8N0011514  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: With / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 215/55R17  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Chao Yang  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 29/11/22  
Survey held at Comfort Lym  
Des. of Damages Front / Rear / O/S / N/S / U/C / Rooftop or Rear 6/s  
The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?  
2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Insp (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S + RS. \$ \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL \_\_\_\_\_

Rep. Format: \_\_\_\_\_  
Lump Sum / L.B.H. / \_\_\_\_\_

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

|                               |                                            |                    |                   |
|-------------------------------|--------------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                                | Ref. No:           |                   |
| Policy No:                    |                                            | Date of Loss:      | 26/11/2022        |
| Vehicle Reg. No.:             | <b>SHA3909J</b>                            | Driveable?         | YES               |
| Party At Fault:               | UNKNOWN                                    |                    |                   |
| Make/Model:                   | BYD ALL-NEW E6, 2.0 (A)                    | Vehicle Reg. Date: | 31/05/2022        |
| Vehicle Colour:               | BLUE                                       | Gen Condition:     | GOOD              |
| Engine No:                    | 1814TZXS321037339                          | Chassis No:        | LC0CE4DC8N0011514 |
| Odometer:                     | 0 KM                                       |                    |                   |
| Paint Type:                   |                                            |                    |                   |
| List Item Discount:           | 20.00 %                                    |                    |                   |
| Total Loss?                   | <b>NO</b>                                  |                    |                   |
| Est. Duration of Repair (day) | 4                                          |                    |                   |
| Present Location:             | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) |                    |                   |

**COST OF CLAIMS**

|                          | Amount          |
|--------------------------|-----------------|
| Parts                    | 2,119.60        |
| Miscellaneous Items      | 11.00           |
| Labour                   | 850.00          |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>2,980.60</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>208.64</b>   |
| <b>Nett Amount (S\$)</b> | <b>3,189.24</b> |

**This claim is handled by: JUMANI BIN MASUDIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2022)**Parts:** 143 BYD ALL-NEW E6 2.0 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA3909J/28/11/2022 16:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No. | Qty | Part No. | Particulars               | %Disc                                        | %Depr | Amount            |
|-----|-----|----------|---------------------------|----------------------------------------------|-------|-------------------|
| 1   | 1   |          | *REAR BUMPER ASSY         | 20.00                                        | 0.00  | de ✓ *2,013.75 FL |
| 2   | 1   |          | *REAR BUMPER MOULDING     | 20.00                                        | 0.00  | de ✓ *528.75 FL   |
| 3   | 10  |          | *REAR BUMPER CLIPS        | 20.00                                        | 0.00  | de ✓ *22.00 FL    |
| 4   | 1   |          | *REAR BUMPER MAT          | 0.00                                         | 0.00  | de ✓ *50.00 F     |
| 5   | 1   |          | *REAR BUMPER LINE STICKER | 0.00                                         | 0.00  | de ✓ *18.00 F     |
|     |     |          |                           | <b>Sub Total (S\$)</b>                       |       | <b>2,632.50</b>   |
|     |     |          |                           | <b>- List Item Discount on L Items (S\$)</b> |       | <b>512.90</b>     |
|     |     |          |                           | <b>Total Parts (S\$)</b>                     |       | <b>2,119.60</b>   |

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA3909J/28/11/2022 16:39. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount |
|----------------------------|-----|----------------------|--------|
| <b>Miscellaneous Items</b> |     |                      |        |
| 1                          | 1   | OD/TP Case (Insurer) | 11.00  |
| Sub Total (S\$)            |     |                      | 11.00  |

## Estimates on Labour

| No                      | Particulars                 | Lab.Type | Amount      |
|-------------------------|-----------------------------|----------|-------------|
| <b>Labour Items</b>     |                             |          |             |
| 1                       | PANEL BEATING               | New      | 400. 500.00 |
| 2                       | SPRAYPAINT                  | New      | 250 300.00  |
| 3                       | REMOVE/REFIX REVERSE SENSOR | New      | 30 50.00    |
| Gross Labour Cost (S\$) |                             |          | 850.00      |

ComfortDelGro Engineering Pte Ltd/SHA3909J/28/11/2022 16:39. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfilm 97495747  
wp' 29/11/22 @ 10am -  
p/p heavy before paint  
2 days  
tanfilm e/1st auto-con

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701  
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

### Workshops

59 Loyang Drive Singapore 508969 24 Senoko Loop Singapore 75815  
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 72  
45 Pandan Road Singapore 609286 501 Yehun Industrial Park A Singapore  
326 Ubi Road 3 Singapore 408649

Date/Time: 28.11.2022 15:55

Page : 1

Team: ARC Repair TP(CLS0)1

### JOB CARD

Sales Order: 5328064

JC NO: 305538070

#### CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD  
CUSTOMER NO. 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
TEL. (R) 65508755 (O)

DISCOUNT CARD NO.


|                                   |                                  |
|-----------------------------------|----------------------------------|
| REGN NO:<br>SHA3909J              | MILEAGE                          |
| MAKE:<br>BYD                      | FUEL<br>E.....1/2.....           |
| MODEL<br>NEW E6                   | DATE/TIME IN<br>26.11.2022 20:30 |
| YR OF MANU.<br>31.05.2022         | TARGET DATE                      |
| CHASSIS CODE<br>LCOCE4DC8N0011514 | COMPLETION DATE/T                |

#### JOB DESCRIPTION

Accident Date: 26.11.2022  
NATURE: 3P.26.11.22

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:  
I/C No.:  
Vehicle No.: SHA3909J J TOKIO

Vehicle No.: SHA3909J

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard