



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011951/Awy3m4 Date: 03/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBP 8730R	Veh. Inspected	SLE 7434S
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2204327/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	29/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WWWZZZAUZGW225877	Colour	BLUE
	Odometer	71357 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	MICHELIN	6 mm
	L/H Front Tyre	225/40 R18	MICHELIN	6 mm
	R/H Rear Tyre	225/40 R18	MICHELIN	6 mm
	L/H Rear Tyre	225/40 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/11/2022	Inspection Date	30/11/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	