OCC ALA 230	11953/Awy3
	IGNMENT
From: Date:	Veh No: SNC879+H-Yr Regn: 2021, Nov
Estimated Cost:	Type: M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Meredes Berz CLA 180 c.c 1332
t Workshop m/s	Colour While A/C: Insured / Std / NI / NA
	Sp.Reading 15063 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: WIKI183842N+66/0/
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: (norder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 225/45 R18-
(Policy Condition)	R: 25/45 R18
Remark: The veh had commenced its N/S O/S	BS / DÚN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF Centrental
al. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
BIA / PR Seen: Consistent?: Yes or No	L/Bal. 26 mm L/Bal. 26 mm
st. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 29/11/22
um Sum: % 3 Val.: Yes or No	Survey held at JL Perfect.
A / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
TP AL.	· · · · · · · · · · · · · · · · · · ·
MV:	
Nett:	<u> </u>
7,000	
Notified The Develop	
ate/Time, File Pass to? : Preli. Report	Days Of Repair:
ate/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Fee	Transportation: Site Insp (\$)s+Rssi
/~ c. \$0.5 ff = 5-50;	Interview (6)
	Filler VIOW (#) Photos

SC1N22BT0003 / City Auto Pte Ltd ENTRY DATE & TIME: 29/11/2022 11:39 (SGT) SUBMITTED BY: Jason Quak VERSION: 1 (29/11/2022 11:39 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 5. Any raise reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/11/2022 11:39 (SGT) Reported by Date of Accident 27/11/2022 13:00 (SGT) Exact Location of Accident Singapore Additional Location Information CARPARK OF 100AM SHOPPING MALL Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNC8794H

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner RAMEYSH DANOVANI BIN MAHM NRIC No SXXXX400B **Email Address** rdanovani@gmail.com Mobile Phone No (Phone) +65-91133971 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Mercedes Model C180 Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto 1332

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd. Policy Number / Cover Note Number SP2003267998-01

DRIVER

Name of Driver RAMEYSH DANOVANI BIN MAHM NRIC No SXXXX400B Date Of Birth 14/11/1978 Occupation Indoor

Date Of Driving Pass 17/04/2008 Driving experience 14 YEARS AND 7 MONTHS Gender Mobile Number (Phone) +65-91133971 Alt, Phone Number **Email Address** rdanovani@gmail.com Address 1 SERANGOON NORTH VIEW #14-07 Address complement Postcode 554343 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Side Swipe Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMG367B Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Private car

Vehicle Category

Name of Driver Contact Number

Address	_
Address complement	-
Postcode	-
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve discrincura of cartain personal data about me to bring about delivery of the came as well as on the external cover of envelopen Imal. packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre

CITY AUTO PTE LTD Blk 8 Sin Ming Road #01-58/60/62 Sin Ming Ind Est Singapore 575643 Tel: 6453 1719 Fax: 6453 7944 (Chins Section)

Sketch Plan

A= SNC8794H B= SMG 367B Carport Of 100 Am Shopping Mall

		1	/
1			
			-
			-

	/		
	,	,	
	Refer to attack	- 2cl	
	/		
	. /		
	<u> </u>		
			-
7			

I/We declare the foregoing particulars are true in every respect.

Diver's Signature (If driver is not the policyholder) / Date & Time

CITY AUTO PTE LTD

Bik 8 Sin Ming Road

#01-58/60/62 Sin Ming
Singapore 57564

Tel: 6453 1234 Fax: 6453 7944

(Claims Section).

Witnessed by Reporting Centre Personnel

On 27.11.2022 at about 13:00 hours at Carpark of 100 AM Shopping Mall, I was travelling straight at the above mentioned location and suddenly vehicle (B) coming out from the carpark lot without checking the oncoming traffic condition. I slowed down and stopped my vehicle (A), yet vehicle (B) still collided onto the front left hand side portion of my vehicle (A).

Vehicle (A): SNC 8794H

Vehicle (B): SMG 367B

Encya Engrace/