

Service Request Details

Claim	S2M04FC2
Reference	CS3/ASM22011955/Gqp3e2
Loss Date	19 November 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	23 Nov 2022 9:41:46 AM
Request Date	29 November 2022
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident	SNG237G
Vehicle	
Registration #	
Make	TPVD
Model	Toyota

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Invoice



Surveyor/ Assessor expense



Upload Documents

Already Attached

NAME

DATE UPLOADED

NAME

TYPE

SUBTYPE

AUTHOR

DATE UPLOADED

[HSB-LKKInvoice-AC2302329.pdf.pdf](#)

Invoice

Surveyor/ Assessor
expenseLKK AUTO CONSULTANTS
PTE LTD (TP)

17 April 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	17 April 2023
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 April 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 April 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 April 2023
 AXA Immediate Advice - SNG237G (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2023
 SNG237G TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	29 November 2022
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	29 November 2022
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	29 November

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
				2022
 SJ0G22BM000Q-01-SHD3266P.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	23 November 2022