

ASS. REC. BY:

REF:

MSG/ 2201197011ey

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SFA 1050R SLP 7151A

Policy No.

100/415827

Claims No.

292314

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

855K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

3/4

21 Sep @ 4800 Cnhw

Cred 6747.30, 5870

Veh No:

SBH 8888L

Yr Regn:

09, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 528i GT

C.C.

1997

Colour

M. D. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

132368

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBASZ 82020DZ 35833

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

245/45R19

R:

275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

25/11/22

D.O.I.

5/12/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 24/4/23-typist

Days Of Repair:

6

Resurvey No. of Trlp:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) S - RS \$

) Fuel

) Others

TOTAL

Report Format: Merimen

Lump Sum / L.B. (\$ 4800)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 003D

Vehicle Details

Vehicle No.: SBH8888L
Vehicle to be Exported: No
Intended Deregistration Date: 03 Dec 2022
Vehicle Make: B.M.W.
Vehicle Model: 528I GT AT D/AB DSC LED SR NAV
Primary Colour: Grey
Manufacturing Year: 2013
Engine No.: A2510587N20B20A
Chassis No.: WBASZ62020DZ35833
Maximum Power Output: 180.0 kW (241 bhp)
Open Market Value: \$55,658.00
Original Registration Date: 30 Sep 2013
First Registration Date: 30 Sep 2013
Transfer Count: 1
Actual ARF Paid: \$72,185.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Sep 2023
PARF Rebate Amount: \$36,092.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2023
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$80,000.00
COE Rebate Amount: \$6,339.00
Total Rebate Amount: \$42,431.00

The information contained herein is correct as at 03 Dec 2022

OK

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DHOM120051242001	Excess:	\$750/- NAMED DRIVERS - OPTION 2 \$1500/- OTHERS
Type of Cover	COMPREHENSIVE		\$3000/- APPL TO <25 YRS & OR <3YRS EXP
Vehicle Number	SBH8888L		\$100/- WINDSCREEN DAMAGE CLAIM
Name of Insured	KOH THONG KIAT		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 30 March 2022 to 29 March 2023
Hire Purchase MAYBANK SINGAPORE LIMITED

Engine# A2510587N20B20A
Chassis# WBASZ62020DZ35833

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]
AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
 - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
 - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD



FSCPP Date : 28/03/2022

For the Company

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/11/2022 13:48 (SGT)
Reported by	Both
Date of Accident	25/11/2022 09:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BLK 16 KALLANG PLACE OPEN CAR PARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBH8888L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KOH THONG KIAT
NRIC No	S1539003D
Email Address	kohjackson@gmail.com
Mobile Phone No	(Phone) +65-96341211
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	528i GT AT D/AB DSC LED SR NAV
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DHOM120051242000

DRIVER

Name of Driver	KOH THONG KIAT
NRIC No	S1539003D
Date Of Birth	26/02/1962
Occupation	Indoor

Date Of Driving Pass	12/11/1981
Driving experience	41 YEARS
Gender	Male
Mobile Number	(Phone) +65-96341211
Alt. Phone Number	-
Email Address	kohjackson@gmail.com
Address	6 JALAN TUA KONG #02-12
Address complement	-
Postcode	457269
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

NOTE: VEHICLE REPAIR AT OWNER W/SHOP - COMPLETE VMS

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFG1050R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	HEIN HUI LANG
-	S1525921C
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP7151A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAN AI LING
-	S845650E
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"insurers"**), the Insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
(collectively the **Purposes**).
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



vJun2022

Describe Circumstance of the Accident

my ~~last~~ vehicle was stationary parked at
Buk 16 Kallang place at 0930am. SF91050R
parked on my RH Carpark.

SIP7151A was on coming near SF91050R.

Suddenly, SIP7151A accelerate onto SF91050R
the impact was huge that SF91050R collided onto
my vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
S'pore 068807

Estimate bill : TT 43 / 22 / TP / WT

Registration No : SBH8888L

Attn : Motor Claims Department
Tel : 68272888
Fax : 68277800

Make / model : BMW 528i GT

Mileage :

Date : 03 / 12 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLP7151A AND SBH8888L ALONG
BLK 16 KALLANG PLACE OPEN CARPARK ON 25 NOVEMBER 2022 AT ABOUT 0930HRS.**

1pc	Rear RH door	\$	R ₁	1,673.00	✓
1pc	Rear RH door outer handle	\$	Sm	940.00	X
1pc	Rear RH door glass outer sliding moulding	\$	Sm	60.00	X
1pc	Rear RH door glass inner sliding moulding	\$	Sm	130.00	✓
1pc	Rear RH door glass channel	\$	Cur	41.00	✓
1pc	Rear RH door weather strip (Standing)	\$	Di	81.00	✓
1pc	Rear RH door weather strip (Small)	\$	Di	139.00	✓
1pc	Rear RH door weather strip (Big) 361.20	\$	Cur	576.00	✓
1pc	Rear RH door inner lock	\$	R	1,349.00	X
2pcs	Rear RH door hinge	(Each \$199.00)	R	398.00	✓
1pc	RH door side skirt	\$	R	756.00	✓
1pc	RH door side skirt rear bracket	\$	Di	121.00	✓
1pc	Rear RH fender	\$	R	1,592.00	✓
1pc	Rear RH fender cowl.	\$	Cur	141.00	✓
	Sub total :	\$		7,997.00	
	Less 10% discount :	\$		799.70	
	A total :	\$		7,197.30	
Special net items :					
1pc	Rear RH tyre, Pirelli P Zero, 275 / 40 R19 Run Flat tyre	\$	Sm	800.00	X
	B total :	\$		800.00	

Remove and transfer rear RH door necessary attachment spart part items.

Remove and transfer rear RH fender necessary attachment spart part items.

Remove and refit rear RH door, rear RH door outer handle, rear RH door glass outer sliding moulding, rear RH door glass inner sliding moulding, rear RH door glass channel, rear RH door weather strip (Standing), rear RH door weather strip (Small), rear RH door weather strip (Big), rear RH door inner lock, rear RH door hinge, rear RH door side skirt, rear RH door side skirt rear bracket.

Heat / weld / cut / renew rear RH fender, heat / weld / panel beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

\$ 2,000.00

Total amount of Page 3 :
Tropical Tech Automobile Services

\$ 7,997.30

(Authorised Signature)
William Tan

Not Withheld
11 Pm @ 4800h
Recovery After Repair
6 days

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
S'pore 068807

Attn : Motor Claims Department
Tel : 68272888
Fax : 68277800

Estimate bill : TT 43 / 22 / TP / WT

Registration No : SBH8888L

Make / model : BMW 528i GT

Mileage :

Date : 03 / 12 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLP7151A AND SBH8888L ALONG
BLK 16 KALLANG PLACE OPEN CARPARK ON 25 NOVEMBER 2022 AT ABOUT 0930HRS.**

Remove and refit rear RH tyre.

Balancing rear RH wheel.

Conduct wheel alignment test.

Diagnostic and reset rear RH door electric components by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear RH door, rear RH door outer handle, rear RH door
hinges, RH door side skirt, rear RH fender.

Balance amount brought from Page 1 :

Grand final amount :

\$	nn	50.00	X
\$		120.00	601
\$		100.00	601
\$		80.00	201
\$		200.00	301
\$		1,000.00	6601
\$		7,997.30	
\$		9,547.30	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

(Authorised Signature)
William Tan