

ASS. REC. BY:

REF:

MSG/ 2201197011ky

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SBH 8888L

Yr Regn:

09, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 528i GT

c.c

1997

Colour:

M. D. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

132368

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBASZ 820200Z 35833

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

245/45R19

R:

275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

25/11/22

D.O.I.

5/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fix. Ins

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
S'pore 068807

Attn : Motor Claims Department
Tel : 68272888
Fax : 68277800

Estimate bill : TT 43 / 22 / TP / WT

Registration No : SBH8888L

Make / model : BMW 528i GT

Mileage :

Date : 03 / 12 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLP7151A AND SBH8888L ALONG
BLK 16 KALLANG PLACE OPEN CARPARK ON 25 NOVEMBER 2022 AT ABOUT 0930HRS.**

1pc	Rear RH door	\$	1,673.00	✓
1pc	Rear RH door outer handle	\$	940.00	X
1pc	Rear RH door glass outer sliding moulding	\$	60.00	X
1pc	Rear RH door glass inner sliding moulding	\$	130.00	✓
1pc	Rear RH door glass channel	\$	41.00	✓
1pc	Rear RH door weather strip (Standing)	\$	81.00	✓
1pc	Rear RH door weather strip (Small)	\$	139.00	✓
1pc	Rear RH door weather strip (Big)	\$	576.00	✓
1pc	Rear RH door inner lock	\$	1,349.00	✓
2pcs	Rear RH door hinge	(Each \$199.00) \$	398.00	✓
1pc	RH door side skirt	\$	756.00	✓
1pc	RH door side skirt rear bracket	\$	121.00	✓
1pc	Rear RH fender	\$	1,592.00	✓
1pc	Rear RH fender cowl.	\$	141.00	✓
	Sub total :	\$	7,997.00	
	Less 10% discount :	\$	799.70	
	A total :	\$	7,197.30	

Special net items :

1pc	Rear RH tyre, Pirelli P Zero, 275 / 40 R19 Run Flat tyre	\$	800.00	X
	B total :	\$	800.00	

Remove and transfer rear RH door necessary attachment spart part items.

Remove and transfer rear RH fender necessary attachment spart part items.

Remove and refit rear RH door, rear RH door outer handle, rear RH door glass outer sliding moulding, rear RH door glass inner sliding moulding, rear RH door glass channel, rear RH door weather strip (Standing), rear RH door weather strip (Small), rear RH door weather strip (Big), rear RH door inner lock, rear RH door hinge, rear RH door side skirt, rear RH door side skirt rear bracket.

Heat / weld / cut / renew rear RH fender, heat / weld / panel beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

\$ 2,000.00

Total amount of Page 3 :

Tropical Tech Automobile Services

\$ 7,997.30

(Authorised Signature)
William Tan



Not Notarised
6 days
Paying After Repair

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
S'pore 068807

Attn : Motor Claims Department
Tel : 68272888
Fax : 68277800

Estimate bill : TT 43 / 22 / TP / WT

Registration No : SBH8888L

Make / model : BMW 528i GT

Mileage :

Date : 03 / 12 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLP7151A AND SBH8888L ALONG
BLK 16 KALLANG PLACE OPEN CARPARK ON 25 NOVEMBER 2022 AT ABOUT 0930HRS.**

Remove and refit rear RH tyre.	
Balancing rear RH wheel.	\$ 50.00 <i>X</i>
Conduct wheel alignment test.	\$ 120.00 <i>601</i>
Diagnostic and reset rear RH door electric components by HHT	\$ 100.00 <i>601</i>
To check and refit rear tail lamp wiring harness.	\$ 80.00 <i>201</i>
Under coating on rear damaged portion.	\$ 200.00 <i>301</i>
Putty / primer application, spray painting rear RH door, rear RH door outer handle, rear RH door hinges, RH door side skirt, rear RH fender.	\$ 1,000.00 <i>6601</i>
Balance amount brought from Page 1 :	\$ 7,997.30
Grand final amount :	\$ 9,547.30

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ('GIA') may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the 'Personal Information') and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the 'Insurers'), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the 'Purposes')
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/11/2022 13:48 (SGT)
Reported by	Both
Date of Accident	25/11/2022 09:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BLK 16 KALLANG PLACE OPEN CAR PARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBH8888L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KOH THONG KIAT
NRIC No	S1539003D
Email Address	kohjackson@gmail.com
Mobile Phone No	(Phone) +65-96341211
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	528i GT AT D/AB DSC LED SR NAV
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DHOM120051242000

DRIVER

Name of Driver	KOH THONG KIAT
NRIC No	S1539003D
Date Of Birth	26/02/1962
Occupation	Indoor