



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2207953

INV Date 27/12/2022

Reference CS/EQI22011985/Rvy3m4

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SLH 2969H
Insured Veh. SLP 9422E
Claim No. DM22HO02065
Policy No.
Accident Date 28/11/2022
Inspection Date 30/11/2022

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	300.00
GST (7%)	21.00
Grand Total	321.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Ref: CS/EQI22011985/Rvy3m4

Date: 27/12/2022

Code: EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 9422E	Veh. Inspected	SLH 2969H
Policy No.		Coverage (\$)	0.00
Claim No.	DM22HO02065	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	30/11/2022

2. Vehicle Particulars & Condition

Make & Model	SKODA KODIAQ 2.0 TSI S/R	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	TMBMD9NS9L8016840	Colour	BLUE
Odometer	29939 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R20	PIRELLI	6 mm
L/H Front Tyre	235/45 R20	PIRELLI	6 mm
R/H Rear Tyre	235/45 R20	PIRELLI	6 mm
L/H Rear Tyre	235/45 R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/11/2022	Inspection Date	30/11/2022
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2969H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	UNBEKANNT LHS FRT DOOR (SN)	TO REPAIR SEE LABOUR	4,077.18	-
1	UNBEKANNT LHS FRT DOOR SEAL (SN)	NOT NECESSARY	117.03	-
1	COUPLING P (SN)	NOT NECESSARY	3.86	-
2	BOLT WITH POLYGON SOCKET @\$5.62 (SN)	NOT NECESSARY	11.24	-
2	UNBEKANNT BOLT @\$1.23 (SN)	NOT NECESSARY	2.46	-
1	PROTECTION LHS FRT DOOR LOWER PROTECTOR (SN)	NOT NECESSARY	561.51	-
4	GROMMET @\$1.50 (SN)	NOT NECESSARY	6.00	-
1	UNBEKANNT LHS REAR DOOR (SN)	BUCKLED	4,077.18	4,077.18
1	UNBEKANNT DOOR SEAL (SN)	NECESSARY	117.03	117.03
1	COUPLING P (SN)	NECESSARY	3.86	3.86
1	ALU-LAMIN.INSULATION DOOR INSULATION (SN)	NECESSARY	43.65	43.65
2	UNBEKANNT BOLT @\$1.23 (SN)	NECESSARY	2.46	2.46
2	BOLT WITH POLYGON SOCKET @\$5.62 (SN)	NECESSARY	11.24	11.24
1	FENSTERHEBER LHR DOOR REGULATOR (SN)	NOT NECESSARY	401.93	-
1	COVER (SN)	NOT NECESSARY	15.36	-
1	DOOR EDGE (SN)	NOT NECESSARY	209.91	-
1	PROTECTION LHS REAR DOOR LOWER PROTECTOR (SN)	SCRATCHED	552.20	552.20
6	GROMMET @\$1.50 (SN)	NECESSARY	9.00	9.00
1	LHR WHEEL ARCH TRIM (SN)	SCRATCHED	271.18	271.18
6	GROMMET @\$1.84 (SN)	NECESSARY	11.04	11.04
1	ALLOY WHEE (SN)	SCRATCHED	2,670.00	2,670.00
1	RUBBER VALVE (SN)	NECESSARY	3.85	3.85
			13,179.17	7,772.69
LABOUR				
B&P CHECK SHORT CIRCUIT/HARNESS REPAIR.			280.00	280.00
B&P DIAGNOSIS AND PROGRAMMING.			480.00	480.00
B&P WHEEL ALIGNMENT.			360.00	360.00
R&R RIM & BALANCE.			50.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR. INCLUSIVE OF THE REPAIR OF UNBEKANNT LHS FRT DOOR.		5,040.00	2,100.00
	SPRAY PAINT.		4,800.00	2,000.00
	TRANSFER DOOR MECHANISM.		840.00	420.00
			11,850.00	5,690.00
GRAND TOTAL			25,029.17	13,462.69
RECOMMENDED COST OF REPAIRS				13,462.69

Report Ref No. CS/EQI22011985/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/11/2022 16:10 (SGT)
Reported by Owner
Date of Accident 28/11/2022 12:32 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG CLIFTON VALE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH2969H

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner KHOO JOANNA DEBBY
NRIC No SXXXX233D
Email Address jo.khoo@gmail.com
Mobile Phone No (Phone) +65-91540866
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Skoda
Model Kodiaq
Variant Kodiaq L&K 2.0 I TSI 132kW -WC MY20
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2000

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number SP2000691914

DRIVER

Name of Driver STEVE LEONG KOK CHEONG (LIANG GUOCHANG)
NRIC No SXXXX052A
Date Of Birth 09/05/1974
Occupation Indoor

Date Of Driving Pass	06/08/2001
Driving experience	21 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96330311
Alt. Phone Number	-
Email Address	steve.leong@hotmail.com
Address	123 SERANGOON NORTH AVE 1
Address complement	#04-163
Postcode	550123
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	FBL5262R
Insurance Company of Other Vehicle Owned by Driver	Direct Asia Insurance (Singapore) Pte Ltd

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	KHOO JOANNA DEBBY
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP9422E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LAU HANG WOEI
NRIC No	SXXXX412E
Contact Number	(Phone) +65-92292689
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


28.11.22 1:47pm
Policyholder's Signature / Date & Time


28/11/22 @ 1:47pm
Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



vJun2022

1

Describe Circumstance of the Accident

On Mon 28 Nov 2022, my husband Steve Leong Kok Cheong was driving our car towards 24 Lynwood Grove. I was in the passenger seat. We were driving along Clifton Vale which is a 1-lane road and there were no cars behind us. ~~See~~ As we were approaching the small perpendicular side road also called Clifton Vale, there was a black car SLP9422E which did not stop at the stop line and turned right and hit our car on our left. Both our front and rear doors on the left were damaged. We took photographs and have in-car camera footage when the other car SLP9422E hit us. According to the in-car camera, the accident happened around 12.32 - 12.33 pm.

Declaration

I/We declare the foregoing particulars are true in every respect.

 28.11.22 1:55pm
 Policyholder's Signature / Date & Time


 Actual Driver's Signature (if driver is not the policyholder) / Date & Time 28/11/22 1:55pm


 Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 2969H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 2969H

RE-INSPECTION










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

