

ASS. REC-BY: T. J. M.

REF: CS/CT12701999/Twp3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / MS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SLP536ST Yr Regn: 217, June.  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: M. F. Whish ancer EX C.C. 1590  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 105007 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: July SRCY / AG 4006872  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modl: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 205/60R16  
R: W  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 01/12/22  
Survey held at CPC Up.  
Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or Tr + O/S  
The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: 960K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report  
1) ☐ : Final Report  
Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

Report Format : \_\_\_\_\_  
Lump Sum / L.B.A. (?) \_\_\_\_\_



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Lim Teck Hock  Blk 928 Hougang Street 91 #09-53 Singapore 530928  Contact No Mobile: 96529703	Cust No/Name /Yap Hwee Hwang Reg No/Reg Date SLP5363T / 09/06/2017 Date In/Mileage 29/11/2022/ 105004 Chassis No JMYSRCY1AGU006872 Engine No 4A92CP5273 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim UO2 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	29/11/2022/ 13:53	LER	972 / Mars Ler	13011
Description of Goods / Services					Qty Unit Price Disc% Amount
Z TEXT ACCIDENT ON 29/11/2022 ALONG NEAR BLK 534 PASIR RIS DR 1 OPEN CARPARK OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # YP170L TP INS : CHINA TAIPING					80. 160.00
M SUNDRY TO APPLY SELANT KIT ON NEW PANEL					100 200.00
M SUNDRY TO APPLY ANTI-CORROSION ON ACCIDENT AFFECTED AREAS					✓ 180.00
B WHEELALIGNMENT120L To Conduct Computerize Full Wheel Alignment					✓ 50.00
E PNT88000 WHEEL BALANCING					? 280.00
E PNT88000 TYRE YOKOHAMA AE51 x 1Pc					1920 2560.00
E PNT88000 TO REPLACE FRT BUMPER,RHF FENDER,ETC -TO REPAIR RHF SUPPORT PNL,RHF FENDER APRON,RHF DOOR PANEL,HOOD STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS					2200 3300.00
E PNT98000 SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS					✓ 280.00
A 10028901 TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE COD					80. 100.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM					1.00 739.00 00.00 739.00
M FACE,FR BUMPER					12.00 4.00 00.00 48.00
M RIVET,FR BUMPER					10.00 4.00 00.00 40.00
M CLIP,FR BUMPER					1.00 61.00 00.00 61.00
M COVER,HEADLAMP SUPT PANEL					1.00 15.00 00.00 15.00
M BRACKET,FR BUMPER SIDE,LH					1.00 15.00 00.00 15.00
M BRACKET,FR BUMPER SIDE,RH					1.00 37.00 00.00 37.00
M GARNISH,FR BUMPER,RH					1.00 616.00 00.00 616.00
M LAMP ASSY,SIDE MARKER,RH					

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Lim Teck Hock  Blk 928 Hougang Street 91 #09-53 Singapore 530928  Contact No Mobile: 96529703	Cust No/Name /Yap Hwee Hwang Reg No/Reg Date SLP5363T / 09/06/2017 Date In/Mileage 29/11/2022/ 105004 Chassis No JMYSRCY1AGU006872 Engine No 4A92CP5273 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim UO2 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	29/11/2022/ 13:53	LER	972 / Mars Ler	13011

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY,FOG,FR LH	1.00	308.00	00.00	308.00
M GRILLE,RADIATOR	1.00	272.00	00.00	272.00
M MARK,THREE-DIA	1.00	39.00	00.00	39.00
M HEADLAMP ASSY,RH	1.00	682.00	00.00	682.00
M TANK,WINDSHIELD WASHER	1.00	91.00	00.00	91.00
M MOTOR,WINDSHIELD WASHER(*)	1.00	156.00	00.00	156.00
M GASKET,W/SHLD WASHER TANK	1.00	4.00	00.00	4.00
M SHIELD,FR FENDER,FR RH	1.00	120.00	00.00	120.00
M CLIP,SPLASH SHIELD	10.00	4.00	00.00	40.00
M FENDER,FR RH	1.00	528.00	00.00	528.00
M BRACKET,FR FENDER,RH	1.00	14.00	00.00	14.00
M GARNISH,FR FENDER RH	1.00	57.00	00.00	57.00
M WHEEL,DISC	1.00	1450.00	00.00	1450.00

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Taufik 97495749 / 62563561  
 21/12/22 @ 10:50am  
 #Renew before paint  
 Taufik @ khauto.com  
 WP'

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

7% GST on  
 Net 12,442.00  
 870.94  
 Total Payable 13,312.94

Authorized signatory and company stamp

Acknowledged by Repairer

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 311E

### Vehicle Details

Vehicle No.: SLP5363T  
Vehicle to be Exported: No  
Intended Deregistration Date: 30 Nov 2022  
Vehicle Make: MITSUBISHI  
Vehicle Model: LANCER EX 1.6 AT LED TAIL LAMP  
Primary Colour: Silver  
Manufacturing Year: 2017  
Engine No.: 4A92CP5273  
Chassis No.: JMYSRCY1AGU006872  
Maximum Power Output: 86.0 kW (115 bhp)  
Open Market Value: \$12,375.00  
Original Registration Date: 09 Jun 2017  
First Registration Date: 09 Jun 2017  
Transfer Count: 1  
Actual ARF Paid: \$12,375.00  
**Intended PARF Rebate Details**  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 08 Jun 2027  
PARF Rebate Amount: \$8,662.00  
**Intended COE Rebate Details**  
COE Expiry Date: 08 Jun 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$51,106.00  
COE Rebate Amount: \$23,111.00  
**Total Rebate Amount:** \$31,773.00

The information contained herein is correct as at 29 Nov 2022

OK

Get up to S\$3,100 cashback and realise your dream home



Car Make / Model

Price Range



Depreciation



Year Reg



Vehicle Type



C

Advanced Search

Home » Used Cars » Lake View Credit Pte Ltd » Mitsubishi Lancer EX 1.6A

## Mitsubishi Lancer EX 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



# Lake View Credit Pte Ltd



Price	\$61,800		
Depreciation	\$12,150 /yr View models with similar depreciation	Registration Date	27-Jun-2017 (4yrs 6mths 26days COE left)
Mileage	98,335 km (18.1k /yr)	Manufactured	2017
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$29,985 as of today (change)	ONV	\$12,450
COE	\$46,489	ARF	\$12,450
Engine Cap	1,590 cc	Power	86.0 kW (115 bhp)
Curb Weight	1,284 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

### Features

1.6L MIVEC Engine, 115 BHP, 4 Speed Automatic, Airbag, ABS, Auto Headlights/Rain Sensors, LED DRL, Keyless Entry/Start/Stop, Knockdown Rear Seats. View specs of Mitsubishi Lancer EX (2008-2017)

### Accessories

Leather Seats, 16" Sports Rims, Factory Fitted Audio System, 7" Steering Controls, Solar Film, Reverse Camera/Sensors, Fog Lights.


### Description

Be Assured Its Not Private Hire/Leasing Car, If Not Money Back Guaranteed. Sporty Octane Pearl Blue Lancer 1.6A (Lowest Priced \$11,800 Depreciation, No Gimmicks). Genuine Low Mileage Done 98335km. Totally Like New. 1 Malay Owner. New Paintwork. Road Tax Till Dec 22. 100% Warranty. Free. Call Now!


This car comes with 6-mth Sgcarmart Warranty, the best warranty for your car. Ask the dealer to activate the warranty to start the coverage.



✓ Car comes with 6-mth Sgcarmart Warranty



Location Map



Summary





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	29/11/2022 17:20 (SGT)
Reported by	Both
Date of Accident	29/11/2022 08:20 (SGT)
Exact Location of Accident	534 Pasir Ris Dr 1, Block 534, Singapore 510534
Additional Location Information	Near Blk 534 Pasir Ris Dr 1 Open Space Carpark
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5363T
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LIM TECK HOCK
NRIC No	SXXXX311E
Email Address	lmtkhk@singtel.com
Mobile Phone No	(Phone) +65-96529703
Alternative Phone No	

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Lancer
Variant	EX
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1590

### INSURANCE COMPANY

Name of Insurance Company	MSiG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	A 80474438 QMX

### DRIVER

Name of Driver	LIM TECK HOCK
NRIC No	SXXXX311E
Date Of Birth	15/03/1956
Occupation	Indoor





Date Of Driving Pass	16/08/1977
Driving experience	45 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96529703
Alt. Phone Number	-
Email Address	lmtkhk@singtel.com
Address	BLK 928 HOUGANG STREET 91
Address complement	#09-53 SINGAPORE
Postcode	530928
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT BY MR. LIM TECK HOCK.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP170L
Vehicle Manufacturer	Isuzu
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	TAN CHEONG KHEI
NRIC No	SXXXX624Z

Contact Number	(Phone) +65-97971380
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	LIM TECK HOCK
Gender	Male
Phone No	(Phone) +65-98529703
Address	BLK 928 HOUGANG STREET 91
Address Complement	#09-53 SINGAPORE
Post Code	530928
Approximate Age Years Old	66
Injuries Sustained	-
Injured person in which vehicle?	SLP5363T
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers") the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

10.50 am  
29/4/22  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

#### Sketch Plan



Describe Circumstance of the Accident

Refer to attachments  
by Mr. Tim Teck Hock

Declaration

I/We declare the foregoing particulars are true in every respect.

 10.50am  
29/11/22

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Location:- Near BIK 534 Pasir Dr. 1.

Time & date:- 29/11/22, about 8-20am.

My car - SLP 5363T.

Lorry - YP 170L (Ho Eng Huat Constn. Pte Ltd).

<sup>Lorry</sup>  
Driver - Tan Cheong Khei (H/P:- ~~98376299~~)  
97971380

On 29/11/22 as I was driving my car (SLP5363) along the car park driveway from Pasir Ris Central towards Pasir Dr. 1. As I was approaching the car park entrance there was this lorry (LP170L) stopped at the right side of the driveway. As I was about drive pass this lorry ~~the driver~~ suddenly ~~the turn~~ lorry turn left towards the footpath ~~he did not switch on the left turn signal.~~ and hit into my car ~~front right side~~ right front side. I was ~~shocked~~ shocked for a moment. My car (driver side) was not able to open fully and I have to force open it. Once outside I discovered <sup>the</sup> right front side my car are badly damaged.

No injury

  
29/11/22